STATE OF KANSAS STATE CORPORATION COMMISSION

15-065-01823-0000

WELL PLUGGING RECORD

(ail or Deliver Report to: Conservation Division State Corporation Commission 211 No. Broadway Wichita, Kansas NORTH	Grah	0 m	•		•					
Wichita, Kansas	Location as "N	ri m		~ /						
NORTH	Location as "N	Graham County. Sec. 36 Twp. 10 Rge. 21 (E) W (W								
	Location as "NE/CNWKSWK" or footage from lines NW NE SW Lease Owner Hernam George Kaiser Oil Prod.									
	Lease Name Schneider-A Well No. 1 Office Address 909 Palace Bldg. Tulsa, Okla.									
		Well (completed								
'	Date well con									
	Application for plugging filed Application for plugging approved Plugging commenced Apr. 14									
*	Plugging commenced Apr. 14 19.5 Plugging completed Apr. 15 19.5									
	Reason for abandonment of well or producing formation									
				· · · · · · · · · · · · · · · · · · ·						
		well is abandor								
Locate well correctly on above Section Plat	menced?		the Conserva	ition Division o	r its agents bet	ore plugging was co				
ame of Conservation Agent who supervi			Fabric	lus						
oducing formation		Depth to top	Bottom		Total Depth of	Well 3702 r				
how depth and thickness of all water, oi										
OIL, GAS OR WATER RECORDS						CASING RECORD				
FORMATION	CONTENT	FROM	то	SIZE	PUT IN	PULLED OUT				
FORMATION	CONTENT	FROM	10	8 5/8	192	none				
				5 ½	36931	1046'				
•										
			· · · · · · · · · · · · · · · · · · ·		-	 				
			-							
feet for each plug set. Dumped 2 s.	x. cement led 5½. ca mping pres	on top o	f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pul cement. Pu	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pul cement. Pu	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s. 3616'. Pull cement. Pu	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres	on top o	he character of f Halibu mped in	same and depther in the same a	g from 3	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres Co.	on top o asing. Pu ssure 450	f Halibumped in lbs. Pu	same and depther arton plu 23 sx. gamp furni	g from 3	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres Co.	on top o asing. Pusure 450	f Halibumped in lbs. Pu	same and depther arton plu 23 sx. gamp furni	g from 3 el mud a shed by	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres Co. (If additiona Pipe Pull	on top o asing. Pu sure 450	f Halibumped in lbs. Pu	same and depther arton plu 23 sx. gamp furni	g from 3 el mud a shed by	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres Co.	on top o asing. Pu sure 450	f Halibumped in lbs. Pu	same and depther arton plu 23 sx. gamp furni	g from 3 el mud a shed by	6341 to				
Dumped 2 s 3616'. Pull cement. Pu Cementing	x. cement led 5½. ca mping pres Co. (If additiona Pipe Pull 304 Great	on top o asing. Pu sure 450 al description is nece ing Co. Bend, Ks	f Halibumped in lbs. Pu	same and depther arton plu 23 sx. gamp furni	g from 3 el mud a shed by	6341 to				

CONSERV Wich

YANSAS GEOLOGICAL SOCIETY (5 -065 -01823-0000

KÀNSAS W & LOG BUREAU - KANSAS WELL SAMI KANSAS GEDLOGICAL SOCIETY BUILDING 508 EAST MURDOCK - WICHITA, KANSAS .cc. 36 Herman Geo. Kaiser, Gil Producer

NO. 8 Schneider A

TOTAL DEPTH 37021

сомм. 1/30/55 SHOT OR TREATED

H-30, Inc.

CASINO

20:-0 ...10 15 8 1921

12

13 36961

COUNTY

STATE CORPO? ED

FEB 2 7 1959

CONSERVATION DIVISION

Wichita, Karisas

LOG. NE NE SW

Graham

T. 105 . 21H

2101 K.B.

MISSION

80 Surface Clay & Sand Shalo 625 Shalo, Shells & Iron 1080 1250 Sand Shale, Shells & Red Bod 1545 Anhydrito 1595 Shale, Shells & Red Bed 2175 Shalo, Lim & Salt 2220 Shalo & Lim 3702

FORMATION TOPS

ARBUCKLE

HEBBNER 3338 TORONTO 3360 3379 KANSAS CITY BASE KANSAS CITY 3608 CONGLORERATE 3650

I heroby cortify that this is a true and correct log of the above described well as shown by the drilling reports.

H-30, INC.

By January

STATE OF KANSAS

SS:

3691

COUNTY OF SEDGWICK!

Subscribed and sworn to before me, a notary public, in and for said County and State this lith day of February, 1955.

Kotary Public

By Commission expires February 13, 1956.

PLUGGING FILE SEC 36 T 10 R21W BOOK PAGE 94 LINE 15

Ace Pipe Pulling Co.

License No. 2

Telephone 3602

Box 304

GREAT BEND, KANSAS

PLUGGING RECORD

Moved In Apr. 14,	1958	ere en		Completed	Apr. 15	. 1958
Campana	n George Kaiser (Dil Produc	ers			
x 1 1	alace Bldg. Tulsa					
Lease Schneider		Well No. 8	Cy. Gr	aham	State Ks.	
Legal Description NE	NE SW	Sec. 36 T	wp. 10 Rng			
Total Depth 3702!	Size Pipe 51	Weight	14#			
Casing Cemented At	36 9 3 ¹		With 150			Sacks
Size Surface Pipe 8	5/8					
Cemented At 19	•		With 12	25		Sacks
Other Strings						
Well Plugged Back To		-				
Top Perforations						
Plugging Orders	Dump 2 sx. cemer	nt on top	of Halibu	rton plug.	Pull 51	
	Pump in 23 sx. a					
	Cementing Co.		r			25.75±3
State Superviser	A.D. Fabricius		, , , , , , , , , , , , , , , , , , , ,			
Phone	371 Hill city, K	s.				
Company Representative	Loy Munday	,	.			
Phone	Market 42421 Hay	s. Ks.	2			

AFR 3 0 10.00 PLUGGING

COMPRESSION OF PAGE 9 5/LINE / 6