15-065-01846-0000

FILE SEC 6 T/O R234 BOOK PAGE 26 LINE//

## STATE OF KANSAS STATE CORPORATION COMMISSION Give All Information Completely Make Required Affidavit Mail or Deliver Report to: Conservation Division State Corporation Commission

0

## WELL PLUGGING RECORD

NORTH						23W(E)( $W$
	Location as "N	IE/CNW&SW&"	or footage fro		NE SE Inc.	
		Imperial Johnson	<u> 011 or</u> "B"	namaa,	1110 •	Well No. 2
	Office Address.	780 Fourt		nal Bldg	., Wichit	a 2, Kansas
		Vell (completed		*	Oil Wel	
	Date well con	pleted				ay 12 <sub>19</sub> 58
		plugging filed_		····		arch 2719 59
		plugging approv	and the second s	<del></del>		arch 349 59
		nenced		<u> </u>	عر م المعدد	$\frac{511 + 519 - 50}{500 + 11}$
		ndeament of wel			mmercial	quantities
	Reason for abandonment of well or producing formation Commercial quantities  of oil depleted.  If a producing well is abandoned, date of last production  April 3 19 59					
						e plugging was com
Locate well correctly on above Section Plat	menced?		Yes		· · · · · · · · · · · · · · · · · · ·	
Name of Conservation Agent who super	vised plugging of th	is wellMI	. A. D.	<u>Fabrici</u>	us	- 2078
Producing formation		Depth to top	Botton	n	Total Depth of V	Vell 3970 Fee
show depth and thickness of all water,	oil and gas formatio	ns.				
OIL, GAS OR WATER RECORDS	5				C.	ASING RECORD
FORMATION	CONTENT	FROM	то	SIZE	PUT IN	PULLED OUT
				8-5/8	214'	214'
		,		5-1/2	39781	39781
			<u> </u>			
			<del> </del>			
		<del></del>	1			
					<del></del>	
- 4						
dump baile		pipe ter	sion to			
dump baile Worked & s Worked pip 12 joints Bailed flu	er. Worked that casing the free at complete id and sea	pipe ter at 3220' 3100'. S d pulling led hole	sion to - 3160 tarted casing with mu	30". 0' - 3100 hard. P (total d to 215	ulled 97 joints ! = set	
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b	er. Worked that casing the free at - complete aid and sea pridge with	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks	sion to - 3160 tarted casing with mu cement	30". 0' - 3100 hard. P (total id to 215 . Mud to	ulled 97 joints ' - set o 40' - se	et
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b	er. Worked that casing the free at complete id and sea	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks	sion to - 3160 tarted casing with mu cement	30". 0' - 3100 hard. P (total id to 215 . Mud to	ulled 97 joints ' - set o 40' - se	et
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b	er. Worked that casing the free at - complete aid and sea pridge with	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks	sion to - 3160 tarted casing with mu cement	30". 0' - 3100 hard. P (total id to 215 . Mud to	ulled 97 joints ' - set o 40' - s of cella	et
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b	er. Worked that casing the free at - complete aid and sea pridge with	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks	sion to - 3160 tarted casing with mu cement	30". 0' - 3100 hard. P (total id to 215 . Mud to	ulled 97 joints ' - set o 40' - se	et
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b	er. Worked that casing the free at - complete aid and sea pridge with	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks	sion to - 3160 tarted casing with mu cement	30". 0' - 3100 hard. P (total id to 215 . Mud to	ulled 97 joints ' - set o 40' - s of cella	et
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b	er. Worked that casing the free at - complete aid and sea pridge with	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks	sion to - 3160 tarted casing with mu cement	9 30". 9 - 3100 hard. P 5 (total d to 215 . Mud to to base	ulled 97 joints '- set o 40' - so of cella STATE CORPORA	et r. IVED
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b	er. Worked that casing the free at - complete aid and sea pridge with	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks	sion to - 3160 tarted casing with mu cement	9 30". 9 - 3100 hard. P 5 (total d to 215 . Mud to to base	ulled 97 joints '- set o 40' - so of cella STATE CORPORA	et r. IVED
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b	er. Worked that casing the free at - complete aid and sea pridge with	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks	sion to - 3160 tarted casing with mu cement	9 30". 9 - 3100 hard. P 5 (total d to 215 . Mud to to base	ulled 97 joints ' - set 0 40' - se of cella: STATE CORPORA	et r. IVED IIUN COMMISSION 4 1959
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b	er. Worked that casing the free at - complete aid and sea pridge with	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks	sion to - 3160 tarted casing with mu cement	9 30". 9 - 3100 hard. P 5 (total d to 215 . Mud to to base	ulled 97 joints ' - set 0 40' - se of cella: STATE CORPORA	et r. IVED
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b	er. Worked that casing the free at complete id and sea tridge with tridge with	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks	sion to - 3160 tarted casing with mu cement	9 30". 9' - 3100 hard. P 5 (total d to 215 . Mud to to base	ulled 97 joints ' - set 0 40' - se of cella: STATE CORPORA	et r. IVED IIUN COMMISSION 4 1959
dump baile  Worked & s  Worked pip 12 joints  Bailed flu 10' rock b 10' rock b	er. Worked that casing the free at complete id and sea tridge with the cridge	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks	sion to - 3160 tarted casing with mu cement cement	o 30".  o' - 3100  hard. P  c (total  d to 215  . Mud to  to base	ulled 97 joints ' - set 0 40' - se 0 f cella  STATE CORPORA  AUG	et r. IVED IIUN COMMISSION 4 1959
dump baile  Worked & s  Worked pip 12 joints  Bailed flu 10' rock b 10' rock b	er. Worked that casing the free at complete id and sea tridge with the cridge	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks	sion to - 3160 tarted casing with mu cement cement	o 30".  o' - 3100  hard. P  c (total  d to 215  . Mud to  to base	ulled 97 joints ' - set 0 40' - se 0 f cella  STATE CORPORA  AUG	et r. IVED IIUN COMMISSION 4 1959
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b 10' rock b	er. Worked that casing the free at complete id and sea oridge with oridge with (If addition South Great)	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks west cast Bend, Ka	sion to - 3160 tarted casing with mu cement cement	o 30".  o' - 3100  hard. P  g (total  id to 215  . Mud to  to base  (of this sheet)  ling Co.	ulled 97 joints ' - set 0 40' - se 0 f cella  STATE CORPORA  AUG  CONSERVATE  Wishing	et r. IVED IIUN COMMISSION 4 1959
dump baile  Worked & s  Worked pip 12 joints  Bailed flu 10' rock b 10' rock b  Name of Plugging Contractor  Address  KANSAS	er. Worked that casing the free at complete id and sea oridge with oridge with (If addition South Great)	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks losacks aldescription is necessive to Cast Bend, Ka	sion to - 3160 tarted casing with mu cement cement	o 30".  o' - 3100  hard. Proceeding to 215  c. Mud to base  (of this sheet)  ling Co.	ulled 97 joints ' - set 0 40' - se 0 f cella: STATE CORPORA  CONSERVATION With Harm	et r. IVED IIUN COMMISSION 4 1959 ON DIVISION Kansas
dump baile  Worked & s  Worked pip  12 joints  Bailed flu  10' rock b  10' rock b  Name of Plugging Contractor  Address  STATE OF KANSAS  Raymor  well, being first duly sworn on oath, se	er. Worked that casing the free at complete id and sea tridge with the cridge with the cridge with Great cridge.	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks  al description is neces west Casi Bend, Ka	ssion to - 3160 tarted casing with mu cement cement cement ssary, use BACF ng Pull ansas  SEDGW employee of	o 30".  o' - 3100  hard. P  c (total  d to 215  . Mud to  to base  cof this sheet)  ling Co.	of cella:  STATE CORPORA  AUG  CONSERVATION  Significant  Since contained on the contained of the contained	et r. IVED IIUN COMMISSION 4 1959 VA 1
dump baile  Worked & s  Worked pip  12 joints  Bailed flu  10' rock b  10' rock b  Address  STATE OF KANSAS  Raymon  well, being first duly sworn on oath, so	er. Worked that casing the free at complete id and sea tridge with the cridge with the cridge with Great cridge.	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks  losacks  al description is nece liwest Cast Bend, Ka	ssion to - 3160 tarted casing with mu cement cement cement scan a second coment cement cement cement	o 30".  o' - 3100  hard. P  c (total  d to 215  . Mud to  to base  cof this sheet)  ling Co.	of cella:  STATE CORPORA  AUG  CONSERVATION  Significant  Since contained on the contained of the contained	et r. IVED IIUN COMMISSION 4 1959 VA 1
dump baile  Worked & s  Worked pip  12 joints  Bailed flu  10' rock b  10' rock b  Name of Plugging Contractor  Address  STATE OF KANSAS  Raymor  well, being first duly sworn on oath, se	er. Worked that casing the free at complete id and sea tridge with the cridge with the cridge with Great cridge.	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks  losacks  untry of nowledge of the and correct. So (Signature) B;	ssion to - 3160 tarted casing with must be cement cement cement scement scement scement scement cement	o 30".  o' - 3100  hard. P  c (total  d to 215  . Mud to  to base  Cof this sheet)  ling Co.	consequents  ss.  consequents	et r.  IVED IIUN COMMISSION 4 1959  ON DIVISION Kansas  f the above-describe ad and the log of the KANSAS, INC.
dump baile  Worked & s  Worked pip  12 joints  Bailed flu  10' rock b  10' rock b  Name of Plugging Contractor  Address  STATE OF KANSAS  Raymor  well, being first duly sworn on oath, se	er. Worked that casing the free at complete id and sea tridge with the cridge with the cridge with Great cridge.	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks  losacks  al description is nece liwest Cast Bend, Ka	ssion to - 3160 tarted casing with must be cement cement cement scement scement scement scement cement	o 30".  o' - 3100  hard. P  c (total  d to 215  . Mud to  to base  Cof this sheet)  ling Co.	consequents  ss.  consequents	et r. IVED IIUN COMMISSION 4 1959 VA 1
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b 10' rock b 10' rock b  Name of Plugging Contractor Address  STATE OF KANSAS Raymor well, being first duly sworn on oath, so above-described well as filed and that	er. Worked that casing the free at complete id and sea tridge with the cridge with the cridge with the country of the country	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks  al description is nece west Casi Bend, Ka  UNTY OF  (nowledge of the and correct. So (Signature) B; 780 Folia	ssary, use BACK ng Pull ansas  SEDGW employee of: facts, statem help me God y:	o 30".  o' - 3100  hard. P  c (total  d to 215  . Mud to  to base  Cof this sheet)  ling Co.	consequents  ss.  consequents	et r.  IVED IIUN COMMISSION 4 1959  ON DIVISION Kansas  f the above-describe ad and the log of the KANSAS, INC.
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b 10' rock b 10' rock b  Name of Plugging Contractor Address  STATE OF KANSAS Raymor well, being first duly sworn on oath, se above-described well as filed and that	er. Worked that casing the free at complete id and sea tridge with the cridge with the cridge with the country of the country	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks 10 sacks  UNTY OF Conowledge of the and correct. So (Signature) B; 780 Foli:	ssary, use BACK ng Pull ansas  SEDGW employee of: facts, statem help me God y:	o 30".  o' - 3100  hard. Property of total and to 215  of this sheet)  ing Co.  ICK  ICK  IMPERIA  IMP	consequents  ss.  consequents	et r.  IVED IIUN COMMISSION 4 1959  ON DIVISION Kansas  f the above-describe ad and the log of the KANSAS, INC.
dump baile Worked & s Worked pip 12 joints Bailed flu 10' rock b 10' rock b 10' rock b  Name of Plugging Contractor Address  STATE OF KANSAS Raymor well, being first duly sworn on oath, se above-described well as filed and that	er. Worked that casing the free at complete id and sea tridge with the cridge with Great cond L. Bacor ays: That I have the same are true at the same at the same are true at the	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks  al description is nece west Casi Bend, Ka  UNTY OF  (nowledge of the and correct. So (Signature) B; 780 Folia	ssion to - 3160 tarted casing with must cement cement cement scement scement scement cement cement cement cement cement cement	ing Co.  Cof this sheet)  Ling Co.	Julled 97 joints - set 0 40! - se 0 f cella  STATE CORPORA  AUG  CONSEDUCTO  Wighting  Sherein contained L OIL OF  G. Wichia  Address)  19 5	ot r.  IVED IIUN COMMISSION  4 1959  ON DIVISION  Cansas  f the above-describe and the log of the  KANSAS, INC.  ta 2, Kansa
dump baile  Worked & s  Worked pip  12 joints  Bailed flu  10' rock b  10' rock b  10' rock b  STATE OF KANSAS  Raymor  well, being first duly sworn on oath, so above-described well as filed and that	er. Worked that casing the free at complete id and sea tridge with the cridge with the cridge with the country of the country	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks  al description is nece west Casi Bend, Ka  UNTY OF  (nowledge of the and correct. So (Signature) B; 780 Folia	ssion to - 3160 tarted casing with must cement cement cement scement scement scement cement cement cement cement cement cement	ing Co.  ICK  INVERTIAL  INVERTIA	consequents  ss.  consequents	et r.  IVED IIUN COMMISSION 4 1959  ON DIVISION Kansas  f the above-describe ad and the log of the KANSAS, INC.
dump baile  Worked & s  Worked pip  12 joints  Bailed flu  10' rock b  10' rock b  10' rock b  STATE OF KANSAS  Raymor  well, being first duly sworn on oath, so above-described well as filed and that	er. Worked that casing the free at complete id and sea tridge with the cridge with Great cond L. Bacor ays: That I have the same are true at the same at the same are true at the	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks  al description is nece west Casi Bend, Ka  UNTY OF  (nowledge of the and correct. So (Signature) B; 780 Folia	ssion to - 3160 tarted casing with must cement cement cement scement scement scement cement cement cement cement cement cement	ing Co.  Cof this sheet)  Ling Co.	Julled 97 joints - set 0 40! - se 0 f cella  STATE CORPORA  AUG  CONSEDUCTO  Wighting  Sherein contained L OIL OF  G. Wichia  Address)  19 5	ot r.  IVED IIUN COMMISSION  4 1959  ON DIVISION  Cansas  f the above-describe and the log of the  KANSAS, INC.  ta 2, Kansa
Name of Plugging Contractor  Address  STATE OF KANSAS  Raymor  well, being first duly sworn on oath, sabove-described well as filed and that	er. Worked that casing the free at complete id and sea tridge with the cridge with the cridge with the country of the country	pipe ter at 3220' 3100'. S d pulling led hole 25 sacks 10 sacks  al description is nece west Casi Bend, Ka  UNTY OF  (nowledge of the and correct. So (Signature) B; 780 Folia	ssary, use BACK ng Pull ansas  SEDGW employee of: facts, statem help me God y:	o 30".  o' - 3100  hard. Property of total and to 215  of this sheet)  ing Co.  ICK  ICK  IMPERIA  IMP	consequents  ss.  consequents	et r. IUN COMI 4 1959 N DIVIS Cansas f the above d and the XANSA ta 2,

## DRILLER'S LOG

Imperial Oil of Kansas, Inc. 780 Fourth National Building Wichita 2, Kansas

> Johnson "B" No. 2 NW NE SE Sec. 6-10S-23W Graham County, Kansas

Total Depth: 3978'

Elevation: 2423' RB Commenced: 4-28-58 Completed: Production: 99 BOPD

Contractor: Imperial Oil of Kansas, Inc.

Wichita-2, Kansas

Casing Record: Set 8-5/8" Surface Pipe at 214' with 150 sacks cement.

Figures indicate bottom of formations:

Surface Sand & Shale Shale, Sand & Shells Iron & Sand Sand, Shale & Shells Shale & Shells Anhydrite Shale & Shells Shale & Lime Lime Total Depth	214' 1050' 1100' 1910' 2031' 2070' 2510' 3745' 3978'	Anhydrite Heebner Lansing Rotary Total Depth  STATE CORPC  CONSERVATI Wichita,	2031 (
	÷	Jilla,	Kansas ON

We hereby certify this to be a correct and accurate log of the above described well as shown on the daily drilling reports.

IMPERIAL OIL OF KANSAS, INC.

Sworn to before me this 14th day of May, 1958.

Commission Expires:

December 19, 1960

PLUGGING FILE SEC 6 T/O R-300 BOOK PAGE 26 LINE //