
## KANSAS STATE CORPORATION COMMISSION

## CONSERVATION DIVISION AGENT'S REPORT

TO: Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2, Kansas



File NoCo	ounty: Trego
Location: sw nw se	Sec. 7 Twp. 12 Rge. 22 (E) (W)
Name of Field:	Total Depth: 3925
I have this date completed supervis	sion of plugging of:
Lease Name: Babb "AII	Well No. 1
Operator's Full Name: Davis Bros	3. 2 Transit Omp.
	Tulsa Okla
Plugging Contractor: Transit Co	orp.
Address: OKla. City,	Okla. License No.
Oil WellGas Well	_Input WellD & A
Other well as hereafter indicated:	Dry Hole
Was any delay in plugging operation	ns caused by Conservation Division Agent? Yes No X
If yes how long?	Reason:
Operation Completed: Hour llpm	Day 20 Month Aug. Year 1958
The above well was plugged as follo	ws:
TD-3925 8 5/8 set at 194cwc	
Gunned pitts cir hole with hea	vy mud, set cementing plug at 600' and displace
20 sax cement thru drill pipe,	heavy mud to 180 set cementing plug and
15 sax cement, heavy mud to 40	set and tied cementing plug inplace is sac
hulls and 10 sax cement to bot	tom of cellar.
	Gilbert P. Leiker Signed: What O Leiker
	Conservation Division Agent
Reviewed: Alwa Br	ock_
Field Supervisor Remarks:	08-29-1958