## 4-<u>031928</u>

TO: STATE CORPORATION COMMISSION	API number: 15-195-20,716-00-00
CONSERVATION DIVISION - PLUGGING	<u>NE SE</u> /4 SEC. 10 , 12 S, 22 W
200 COLORADO DERBY BUILDING	1980 feet from S section line
WICHITA, KANSAS 67202	feet from E section line
! !	AKA B Malsam
Operator license# <u>4767</u>	Lease Malsam "P" well # 1
Operator: Ritchie Exploration, Inc.	County <u>Trego</u> Well total depth 4115 feet 133.73
	_ well cocal acpen <u>lillo</u> leet
Suite #1000 Wichita, Kansas 67202	Conductor Pipe: 0 inch 0 0 feet
wichita, kansas 6/202	Surface pipe 8 5/8 Inch @ 205 feet
Aband. oil well $\underline{X}$ , Gas well $\underline{\hspace{1cm}}$ , I	nput well, SWD, D & A
Plugging contractor: Kelso Casing Pu	lling, Inc. License# 6050
Address: Chase, Kansas 67524	; ************************************
Company to plug at: Hour: A.M. Day	y: <u>23</u> Month: <u>May</u> Year: <u>94</u>
Plugging proposal received from: Ric	hard
Were: Order 200 sxs. 60/40 pozmix - 10% gel - 500# hulls Order sand and common cement.	
	<del>                                      </del>
	<del>d a a a a a a a a a a a a a a a a a a a</del>
Plugging Proposal Received by: <u>Carl</u>	Goodrow
Plugging operations attended by agen	t? All[ X ], Part[ ], None[ ]
Completed: Hour: 4:30 P.M, Day: 23, 1	Month: May , Year: 94
Actual plugging report: 8 5/8" set @	205' w/150 sxs. 4 1/2" set @ 4117'
W/200 sys. Prod. Perfs 3978! - 4012	I'. Sand hack to 30201 w/4 eye
common cement on sand with bailer.	Shot at 2600' tight shot and pumped 60 sxs. cement blend with 300# AECE VED
hulls to 2500' - pulled casing to 170	pumped 60 sxs. cement blend with 300# ALCENED  OO'. Pumped 55 sxs. cement blend 15 COLOR C
slurry surface to 1700' with 500# P.	S.I. Pulled casing to 200 circulated PON CON
40 SXS. WICH 200# nulls - cement ble	nd sturry to surrace - pulled casing, ()
Cellar remained full of cement. Used	total 155 sxs. cement with 500# 5/1994
hulls. Plug complete. Remarks:	BADAnhy.plug:YESNO
Condition of casing(in hole):GOOD X	BADAnhy.plug:YES_X_NO
Bottom plug(in place):YES / ,CALC_	NO Dakota plug:YES X NO
Plugged through TUBING, CASING_	Elevation: GL
I die [ ] observe the	plugging. Carl Goodwar
6-7-94	(agent)
DATE.	Form CP-2/3