

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
WICHITA, KANSAS 67217

Rev. 6-3-74
FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

API Number 15 - - (of this well)
Lease Owner John O. Farmer, Inc.
Address P.O. Box 352, Russell, Kansas 67665
Lease (Farm Name) PFEIFER Well No. #1
Well Location NE NW NE Sec. 20 Twp. 10S Rge. 25W (E) (W)
County Graham Total Depth 4090 Field Name Wildcat
Oil Well Gas Well Input Well SWD Well Rotary D & A X
Well Log attached with this application as required Yes
Date and hour plugging is desired to begin 8:00 A.M., 9-4-76

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:
Raymond Kaba Address 807 S. Jefferson, Plainville, Ks.
Plugging Contractor John O. Farmer, Inc. License No.
Address P.O. Box 352, Russell, Kansas 67665

Invoice covering assessment for plugging this well should be sent to:
Name John O. Farmer, Inc.
Address P.O. Box 352, Russell, Kansas 67665

and payment will be guaranteed by applicant or acting agent.
Signed: John O. Farmer
Applicant or Acting Agent
Date: September 10, 1976

RECEIVED
STATE CORPORATION COMMISSION

SEP 15 1976
9-15-1976
Wichita, Kansas

State of Kansas



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

245 North Water
WICHITA, KANSAS 67202

September 7, 1976

WELL PLUGGING AUTHORITY

Well No.	1
Lease	Pfeifer
Description	NE NW NE Sec. 20-10-25W
County	Graham
Total Depth	4090
Plugging Contractor	John O. Farmer, Inc.

John O. Farmer Inc.
Box 352
Russell, Kansas 67665

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,

J. Lewis Brock
J. Lewis Brock, Administrator

Mr. Gilbert Balthazor, P.O. Box 9, Route #1, Palco, Kansas 67657
is hereby assigned to supervise the plugging of the above named well.