KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Oil Producers Inc. of Kansas	License Number: 8061
	License Number: 800 I
Operator Address: 1710 Waterfront Parkway, Wichita, KS 67206	T
Contact Person: Lori Zehr	Phone Number: (316) 681 - 0231
Permit Number (API No. if applicable): 15-175-21643-00-01	Lease Name & Well No.: ALEXANDER 2-14
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SW NE NE NW
Settling Pit Drilling Pit	Sec. 14 Twp. 33 R. 32 East V West
✓ Workover Pit	4806 Feet from North / South Line of Section
	3217 Feet from 🗸 East / West Line of Section
	SEWARD
·	County
Date of closure: 2/11/2009	
Section of the sectio	
Was an artificial liner used? ☐ Yes ☑ No	en e
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
	to a contract of
Mud & shale well bore.	Dron:
	RECEIVED
Mud & shale well bore.	RECEIVED NOV 1 3 2009 KCC WICHITA
Mud & shale well bore. Abandonment procedure of pit:	
Mud & shale well bore. Abandonment procedure of pit:	
Mud & shale well bore. Abandonment procedure of pit:	
Mud & shale well bore. Abandonment procedure of pit:	
Mud & shale well bore. Abandonment procedure of pit: Hauled,dried and restore to normal.	NOV 1 3 2009 KCC WICHITA for Oil Producers Inc. of Kansas (Co.),
Mud & shale well bore. Abandonment procedure of pit: Hauled,dried and restore to normal. The undersigned hereby certifies that he / six is Vice President	NOV 1 3 2009 KCC WICHITA for Oil Producers Inc. of Kansas (Co.),
Mud & shale well bore. Abandonment procedure of pit: Hauled,dried and restore to normal. The undersigned hereby certifies that he / six is Vice President	NOV 1 3 2009 KCC WICHITA for Oil Producers Inc. of Kansas (Co.), the best of his /her knowledge and belief.
Mud & shale well bore. Abandonment procedure of pit: Hauled,dried and restore to normal. The undersigned hereby certifies that he / six is Vice President	NOV 1 3 2009 KCC WICHITA for Oil Producers Inc. of Kansas (Co.),
Mud & shale well bore. Abandonment procedure of pit: Hauled,dried and restore to normal. The undersigned hereby certifies that he / six is Vice President	NOV 1 3 2009 KCC WICHITA for Oil Producers Inc. of Kansas (Co.), the best of his /her knowledge and belief.
Abandonment procedure of pit: Hauled,dried and restore to normal. The undersigned hereby certifies that he / is	NOV 1 3 2009 KCC WICHITA for Oil Producers Inc. of Kansas (Co.), the best of his /her knowledge and belief.
Abandonment procedure of pit: Hauled, dried and restore to normal. The undersigned hereby certifies that he / see is	NOV 1 3 2009 KCC WICHITA for Oil Producers Inc. of Kansas (Co.), the best of his /her knowledge and belief.
Abandonment procedure of pit: Hauled,dried and restore to normal. The undersigned hereby certifies that he / stars is	NOV 1 3 2009 KCC WICHITA for Oil Producers Inc. of Kansas (Co.), the best of his /her knowledge and belief. Signature of Applicant or Agent November, 2009 How A. Zew