STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
Wichita, Kansas 67217

Rev. 3-15-72 FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

STATE CORPORATION COMMISSION

JUL 19 1973

CONSERVATION COMMISSION

Lease Owner	- 1 0 5	1	Wichita, Kansas								
							<del></del>	14//	Sas		
Address	Box 352,	Russell	, Kai	nsas	676	65	,				-
Lease (Farm Name)	Custer						Well No. 3				
Well Location	SE SW SE	Sec.	12	Twp.	10S	Rge,	26W	(E)_		(W)	
County	Sheridan	Total	Depti	4	090'		Fie	ld N	ame_		
Oil WellGas Well											
Well Log filed with an											
Date and hour plugging	r is desired	to begin	J	u1y	14,	1973					
Name of sampany vonvoi	entative sui	hori zed	to be	in c	harge	of r	luggi	lng c	pera	tions:	
Name of company repres											rille as
Dale_Buchheiste	<u>r</u>		Ad	dress	207	' N.	Wash	ing	ton,	Plainy Kans	rille as
	r Jo	ohn O.	Ad Farme	dress	207 Inc.	' N.	Wash	ing	No.	Plainy Kans	
Dale Buchheiste	r Jo	ohn O. 1	Ad Farme Russ	er.	207 Inc. Kar	N.	Wash	ense	No.	Plainy Kans	
Dale Buchheiste: Plugging Contractor Address Invoice covering asse	r Jo Bo ssment for p	ohn O. loox 352.	Ad Farme Russ	er, leell	Inc. Kar	N.	Wash 6766	cense	No.	Plain Kans	
	r Jo Bo ssment for p	ohn O. Jox 352.  lugging tohn O.	Ad Farme Russ his w	dresser, leer, leell ser,	207 Inc. Kar should	N.	Wash 6766	ing cense 55	No.	Plain Kans	



## State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water)
P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

July 16, 1973

## WELL PLUGGING AUTHORITY

Well No.

Lease

Description

County

Total Depth

Plugging Contractor

3

Custer

SE SW SE 12-10-26W

Sheridan

4090

Co. Tools

John O. Farmer, Inc. Box 352 Russell, Kansas 67665

## Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,

J/Lewis Brock, Administrator

Mr. W. L. Nichols Box 157 Morland, Kansas is hereby assigned to supervise the plugging of the above named well.