KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING APPLICATION

Please TYPE Form and File ONE Copy

Form CP-1 March 2009 This Form must be Typed Form must be Signed All blanks must be Filled

OPERATOR: License #: 5056	API No. 15 - 185-23622-00-00
Name: F.G. Holl Company, LLC	If pre 1967, supply original completion date:
Address 1: _9431 E. Central - Suite 100	Spot Description: 97' East & 150' South of
Address 2:	
City: Wichita State: KS Zip: 67206 +	
Contact Person; Franklin R. Greenbaum	Footages Calculated from Nearest Outside Section Corner:
Phone: (316) _684-8481	NE NW SE SW
	County: Stafford County, Kansas
	Lease Name: WATERS Well #: _1
Check One: ☐ Oil Well ☐ Gas Well ☐ OG	Water Supply Well Other:
SWD Permit #: ENHR Permit #:	
Conductor Casing Size: Set at:	,
Surface Casing Size: 8-5/8" Set at: 474'	
Production Casing Size: Set at:	
List (ALL) Perforations and Bridge Plug Sets:	Oddio
Condition of Well: Good Poor Junk in Hole Casing Leak at:	(Stone Corral Formation) erval) RECEIVED
	KANSAS CORPORATION COMMISSION
Is Well Log attached to this application? Yes No Is ACO-1 filed? X Yes	No MAY 1 1 2010
If ACO-1 not filed, explain why:	CONSERVATION DIVISION WICHITA, KS
Plugging of this Well will be done in accordance with K.S.A. 55-101 et. seq. and the Rules	and Regulations of the State Corporation Commission
Company Representative authorized to supervise plugging operations: Rob Long	**************************************
P.O. box 308	Ellinwood State: KS Zip: 67530 +
Phone: (_620) _793-0915	
Plugging Contractor License #: Name:	Duke Drilling Company, Inc.
Address 1: P.O. Box 823 Address	s 2:
City: Great Bend	State: KS zip: 67530 +
Phone: (_620) _793-8366	
Proposed Date of Plugging (if known): 05-04-10	
Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent	1 - 10 ne RT ha
Date: 5/10/2010 Authorized Operator / Agent: Loveness Mpan-	Loveress mpaye
	(Signature)

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

Dist./

No Ets - Als Plugged

Ker