Allied Cementing (If additional description is necessary, use BACK of this form.)

rathole with 15 sxs. mousehole with 10 sxs.

3rd plug at 40' with 10 sx.

1  $\frac{1}{2}$   $\frac{1}{2}$   $\frac{1}{2}$   $\frac{1}{2}$   $\frac{1}{2}$   $\frac{1}{2}$  observe this plugging.

41.5.

(lechnician) Herb Deines

10-27-90