## STATE OF KANSAS STATE CORPOBATION COMMISSION

Give All Information Completely

## 15-167-00280-000

State Corporation Commission 800 Bitting Building Wichita, Kansas	Ru	ssell	Coun	ity. Sec. 34	Twp 11 R	ge 15 $(E)$	<u>''</u> (177
NORTH	· Location as "I	NE/CNW¼SW	4" or footage fr	ty. Sec. 34 om lines 990 1	from south	i, 2310° 1	rom e
	Lesso Owner	- Less Owner B. W. Shindhelm					
	Lease Name	O. Eule	rt	T/	••••••	Well No	<u>.</u>
1 1	Office Address	Box 363	, missell,	Nansas	Dogg Uolo	***************************************	
	Character of	Well (completed	as Oil, Gas or	Dry Hole)	DLA HOTE	•	
i		pleted		ct. 17			19.22
	Application fo	or plugging filed.		ct. 27 ct. 28	***************************************		19.22
	Application 10	r plugging appro nenced	vea N	ov. 1			19. <u></u>
i   i	Plugging com	oleted	N	ov. 4			19. <u></u>
				g formation	No pro	duction	19 .//.
	Tteason for an	andonment of v					**********
	If a producing	well is abando		production			
	Was permission			tion Division or			
Locate well correctly on abov Section Plat	menced?	Yes	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	***************************************	_	- 00 0	
ne of Conservation Agent who	supervised plugging of the	his well	ilton Galy	ardt		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	***********
lucing formation Arbuc	ckle De	pth to top.315	8.1 Botton	3210	Total Depth of	Well_3210_	Fee
w depth and thickness of all w		ons.			•		
IL, GAS OR WATER RECO	OPDS 20190					CASING RE	ממסטי
IL, GAS OR WATER REC	ONDS			r		CASING RE	CORD
Formation	Content	From	То	Size	Put In	Pulled	Out
Arbuckle	water	3186	3193	8 5/8	763	None	
A 1 1 =				4 1/2	3210 <b>'</b>	25121	•••••
Arbuckle	Show of oil	31.60	3166				
Kansas City	water	2848	2854				
······································							
•••••••••••••••••••••••••••••••••••••••							
ducing it into the hole. If ce	ement or other plugs wer plug set. The crushed rock ement plug 2830! and dumped 20 s.	from 3169! to 2790!	to 2830!. Filled homent. Top	me and depth p  Dumped 1  Le with muc of cement	sacks cem	ent with O' to 275 lled hole	feet t
ducing it into the hole. If confidence of the confidence of the hole. If co	ement or other plugs wer plug set. The crushed rock ement plug 2830! and dumped 20 s.	from 3169! to 2790!	to 2830!. Filled homent. Top	me and depth p  Dumped 1  Le with muc of cement	sacks cem	ent with O' to 275 lled hole	feet t
Plugged back wit dump bailer. Ce Set rock bridge	ement or other plugs wer plug set.  Ch crushed rock ement plug 2830' and dumped 20 se.  Set rock brid	from 3169! to 2790! acks of cer	to 2830!. Filled homent. Top	me and depth p  Dumped 1  Le with muc of cement	sacks cem	ent with O' to 275 lled hole	feet to
ducing it into the hole. If confidence of the confidence of the hole. If co	ement or other plugs wer plug set.  The crushed rock ement plug 2830' and dumped 20 s.  Set rock brid	from 3169! to 2790! acks of cer	to 2830!. Filled homent. Top	me and depth p  Dumped 1  Le with muc of cement	sacks cem	ent with O' to 275 lled hole	feet t
ducing it into the hole. If confidence of the confidence of the hole. If co	ement or other plugs wer plug set.  The crushed rock ement plug 2830' and dumped 20 s.  Set rock brid	from 3169! to 2790! acks of cerdige. Dumpe	to 2830!. Filled homent. Top	me and depth p  Dumped 1  Le with muc of cement	sacks cem	ent with O' to 275 lled hole	feet t
ducing it into the hole. If confidence of the confidence of the hole. If co	ement or other plugs wer plug set.  The crushed rock ement plug 2830' and dumped 20 s.  Set rock brid	from 3169! to 2790! acks of cerdige. Dumpe	to 2830!. Filled homent. Top	me and depth p  Dumped 1  Le with muc of cement	sacks cem	ent with O' to 275 lled hole	feet t
ducing it into the hole. If commended the section of the section o	ement or other plugs wer plug set.  The crushed rock ement plug 2830' and dumped 20 s. Set rock brid  (If additional Miller Casing Po	from 3169! to 2790! acks of cerdge. Dumpe	to 2830!. Filled homent. Toped 10 sacks	me and depth p  Dumped 14  Le with muc of cement s of cement	sacks cem from 279 205'. Fi for cap.	ent with O' to 275 lled hole  PCOO N-09-5	1.
ducing it into the hole. If confect for each  Plugged back with dump bailer. Confect for each set rock bridge with mud to 35'	ement or other plugs wer plug set.  The crushed rock ement plug 2830' and dumped 20 s. Set rock brid	from 3169! to 2790! acks of cerdge. Dumpe	to 2830!. Filled homent. Toped 10 sacks	me and depth p  Dumped 14  Le with muc of cement s of cement	sacks cem from 279 205'. Fi for cap.	ent with O' to 275 lled hole  PCOO N-09-5	1.
ducing it into the hole. If ce feet for each  Plugged back wit dump bailer. Ce Set rock bridge with mud to 35'	ement or other plugs wer plug set.  The crushed rock ement plug 2830' and dumped 20 s. Set rock brid  (If additional Miller Casing Po	from 3169! to 2790! acks of cerdge. Dumpe	to 2830!. Filled homent. Toped 10 sacks	me and depth p  Dumped 14  Le with muc of cement s of cement	sacks cem from 279 205'. Fi for cap.	ent with O' to 275 lled hole  PCOO N-09-5	1.
e of Plugging Contractor	ement or other plugs wer plug set.  The crushed rock ement plug 2830! and dumped 20 s. Set rock brid  (If additional Miller Casing Pr Great Bend, Kans	from 31.69 to 2790 to 2790 to 2790 to acks of cerdge. Dumped alling Co. Sas	to 2830!. Filled homent. Toped 10 sacks  wary, use BACK of t	Dumped 4 le with muc of cement s of cement weeks	sacks cem from 279 205'. Fi for cap.	ent with O' to 275 lled hole	1.
e of Plugging Contractor	ement or other plugs wer plug set.  ch crushed rock ement plug 2830' and dumped 20 s. Set rock brid  Miller Casing Pr Great Bend, Kans  , COUN	from 3169! to 2790! acks of cerdge. Dumped  description is necessalling Co. Eas	to 2830!. Filled homent. Toped 10 sacks  ary, use BACK of t (Well plu	Dumped 1. le with muc of cement of cement of cement sof cement light in the second second light in the sec	sacks cem from 279 205. Fi for cap.  nse #12)	ent with O' to 275 lled hole	5 bed well,
e of Plugging Contractor	ement or other plugs wer plug set.  ch crushed rock ement plug 2830' and dumped 20 s. Set rock brid  Miller Casing Pr Great Bend, Kans  , COUN	from 3169! to 2790! acks of cerdge. Dumped  description is necessalling Co. Eas	to 2830!. Filled homent. Toped 10 sacks  ary, use BACK of t (Well plu	Dumped 1. le with muc of cement of cement of cement sof cement light in the second second light in the sec	sacks cem from 279 205. Fi for cap.  nse #12)	ent with O' to 275 lled hole	s bed well,
re OF	ement or other plugs wer plug set.  ch crushed rock ement plug 2830' and dumped 20 s. Set rock brid  Miller Casing Pr Great Bend, Kans  , COUN	from 3169! to 2790! acks of cerdge. Dumped  description is necessalling Co. Eas	to 2830!. Filled homent. Toped 10 sacks  ary, use BACK of t (Well plu	Dumped 4 le with muc of cement s of cement le ging lice r) or (owner or matters herein	sacks cem from 279 205. Fi for cap.  nse #12)	ent with O' to 275 lled hole	s bed well,
re OF	ement or other plugs wer plug set.  Ch crushed rock ement plug 2830' and dumped 20 s.  Set rock brid  Miller Casing Progreat Bend, Kans  COUNTY: That I have knowled a same are true and corrected to the corrected true and corrected to the corrected true and cor	from 3169! to 2790! acks of cerdge. Dumped  description is necessalling Co. Eas	to 2830!. Filled homent. Toped 10 sacks  ary, use BACK of t (Well plu	Dumped 4 le with muc of cement s of cement le ging lice r) or (owner or matters herein	sacks cem from 279 205. Fi for cap.  nse #12)	ent with O' to 275 lled hole	5 bed well,

23-8390-s

PLUGGING STE 34 TIL RISW. BOOK PACE-LLUNG 38

DRILLING RECORD

15-167-00280-000

Well No. 1 Eulert NW SW SE Sec 34-115-15W Russell County, Kansas

Work Commenced 9/2/55 Drilling Commenced 9/2/55 Drilling Completed 9/13/55 Work Completed 9/15/55

## Casing Record

763' of 8-5/8" OD Surface Pipe cemented with 500 sacks.

3210' of  $4\frac{1}{2}$ " OD Casing cemented with 30x sacks.

	WELL LOG
Surface Soil	0.4- 20
	0 to 30
Shale & Gravel	30 to 55
Sand & Shale	55 to 310
Shale & Iron	310 to 375
Sand & Clay	375 to 460
R.B. & Shale	460 to 540
Red Bed	540 to 753
Anhydrite	753 to 804
Red Bed	804 to 980
Shale & Shells	980 to 1225
Shale & Salt	1225 to 1300
Shale	1300 to 1460
Shale & Shells	1460 to 1625
Shale & Lime	1625 to 1645
Shale & Lime Stks	1645 to 1690
Lime & Shale	1690 to 2845
K.E. Lime	2848 to 2852
Lime	2852 to 2894
K.C. Lime	2894 to 2954
Lime	2954 to 2998
Lime & Shale	2998 to 3038
K.C. Lime	3038 to 3068
Lime	3068 to 3150
Conglomerate	3150 to 3166
Lime	3166 to 3193
Cherty Arbuckle	3193 to 3210 TD