KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-5 August 2004 Form must be Typed

EXPLORATION & PRODUCTION WASTETRANSFER

Operator Name: John O. Farmer, Inc.	License Number: 5135
	3133
Operator Address: P.O. Box 352, Russell, KS 67665	
Contact Person: Marge Schulte	Phone Number: (785) 483 - 3145, Ext. 214
Permit Number (API No. if applicable): 15-167-23,378 - CO: CO	Lease Name: Mudd Well Number: #1
Source of Waste: Dike Emergency Pit Workover Pit Burn Pit Steel Pit Spill / Escape Type of waste to be disposed: No. of loads Amount of waste: Reserve Pit Disposal Well Lease Road	Source Location (QQQQ): 130' South 60' West C _ N/2 Sec. 27 Twp. 12S R. 15 East West 1450 Feet from North / South Line of Section 2700 Feet from East / West Line of Section Russell County Other:
If waste is transferred to another reserve pit, is the lease active? Yes No	
Location of waste disposal: Operator Name: John O. Farmer, Inc. Lease Name: Mudd (#2 SWD) Docket No.: D-28,909	Date of Waste Transfer: 3-30-10 License No.: 5135 Sec. 27 Twp. 12S R. 15 East West Russell RECEIVED APR 9 2010 KCC WICHITA
The undersigned herby certifies that he / she is	