

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Stanolind Oil & Gas Co. Address Box 1654, Oklahoma City, Oklahoma
(Applicant)

Lease (Farm Name) Henderson "A" well No. 1 *AJB ecc*

Well Location SW/4 SW/4 NE/4 Sec. 7 Twp. 11 Rge. 17 (E)-(W) W

County Ellis Field Name (if any) Burnett

Total Depth 3430 Oil Gas Dry Hole

Was well log filed with application? No. If not, explain: _____

Will be filed w/plugging report

Date and hour plugging is desired to begin 8:00 A.M. 8-1-53

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired, (Use an additional sheet if necessary) None

Name of the person on the lease in charge of well for owner _____

J. M. Maguire Address Plainville, Kansas

Name of Plugging Contractor To be designated later

Address _____

Invoice covering assessment for plugging this well should be sent to

G. A. Reynolds Address Box 35, Gorham, Kansas

and payment will be guaranteed by applicant.

PLUGGING
FILE SEC 2 11 R 17W
BOOK PAGE 118 LINE 41
AUG 1 1953
CONSERVATION DIVISION
Wichita, Kansas

FILED
AUG 1 1953
CONSERVATION DIVISION
Wichita, Kansas

G. A. Reynolds
Applicant or Acting Agent

Date July 30, 1953



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

August 8, 1953.

Well No.	2-1
Lease	H. Henderson
Description	ON LN LD 7-11-17W
County	Ellis
File No.	210-11

Stanolind Oil & Gas Co.
Box 35
Guthrie, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. when you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Eldon Petty, Box 326, Hays, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

By J. P. Roberts
J. P. ROBERTS

cc: District Plugging Supervisor