

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

1039918

Form CDP-1 April 2004 Form must be Typed

APPLICATION FOR SURFACE PIT

Submit in Duplicate

Operator Name: Apollo Energies, Inc.			License Number: 30481
Operator Address: 10378 N 281 HWY			PRATT KS 67124
Contact Person: Kevin Fischer			Phone Number: 620-672-9001
Lease Name & Well No.: BRACHEAR 1			Pit Location (QQQQ):
Emergency Pit Burn Pit Settling Pit Drilling Pit Workover Pit Haul-Off Pit (If WP Supply API No. or Year Drilled) 15-151-00408-00-00 Is the pit located in a Sensitive Ground Water Are	f Existing, date of 6/23/10 Pit capacity: 200 pa? Yes Artificial Liner?	(bbls)	SE NW NW Sec. 30 Twp. 28 R. 13 East West 990 Feet from North / South Line of Section 990 Feet from East / West Line of Section Pratt County Chloride concentration:mg/l (For Emergency Pits and Settling Pits only) How is the pit lined if a plastic liner is not used?
material, thickness and installation procedure.			9 (feet) No Pit edures for periodic maintenance and determining including any special monitoring. val of fluids and liner inspection.
Distance to nearest water well within one-mile of pit		Depth to shallowest fresh water	
KCC OFFICE USE ONLY Steel Pit RFAC RFAS Date Received: 06/25/2010 Permit Number: 15-151-00408-00-00 Permit Date: 06/25/2010 Lease Inspection: Yes No			



Mark Parkinson, Governor Thomas E. Wright, Chairman Joseph F. Harkins, Commissioner Ward Loyd, Commissioner

June 25, 2010

Kevin Fischer Apollo Energies, Inc. 10378 N 281 HWY PRATT, KS 67124-7920

Re: Drilling Pit Application BRACHEAR 1 Sec.30-28S-13W Pratt County, Kansas

Dear Kevin Fischer:

District staff has inspected the location and has determined that an unsealed condition will present a pollution threat to water resources.

District staff has recommended that the Workover pit be lined. If a plastic liner is to be used it must have a minimum thickness of 10 mil. Integrity of the liner must be maintained at all times.

NO completion fluids or non-exempt wastes shall be placed in the Workover pit.

The free fluids in the Workover pit should be removed as soon as practical after drilling operations have ceased. The fluids should be taken to an authorized disposal well. Please call the District Office at (620) 225-8888 when the fluids have been removed. Please file form CDP-5 (August 2008), Exploration and Production Waste Transfer, through SOLAR within 30 days of fluid removal.

If you have any questions or concerns please feel free to contact the District Office at (620) 225-8888.