4-041616 9-22

TO: \ y	API number: 15 - 6-11	30-
STATE CORPORATION COMMISSION		
CONSERVATION DIVISION - PLUGGING	NE SE SE /4 SEC. 16 , 11 S	, <u>17</u> W
200 COLORADO DERBY BUILDING	990 feet from S section	on line
WICHITA, KANSAS 67202	330 feet from E section	on line
		NIB
		ANB
Operator license# <u>6239</u>	Lease Bemis A	well # 4-4
•		109.55
Operator: Zinzer Oil Company	County Ellis	
		119.53
Address: P.O. Box 211	Well total depth 3371 feet	10 1.
Hays, Kansas 67601	Conductor Pipe: 15 inch @	
	Surface pipe 13 3/8 Inch @	
		w/375 sxs.
Aband. oil well <u>X</u> , Gas well, Inp		
	uo 11011/ D u 11 .	
Plugging contractor: Halliburton Cemen	ting License	#
114991119 Conclusion . Marriada Con Comon	<u> </u>	π
Address: Oberlin, Kansas		
Addiess. Obelling Ransas		
Company to plug at: Hour:8:00A.M. Day:	22 Month: Contombon Vo	are 04
company to prug at: nour: e: ova.m. Day:	<u>zz</u> month: <u>september</u> re	ar: <u>94</u>
Diverging proposal received from Denny	· Tannan	· '
Plugging proposal received from: Perry	Henman	
Company: Zinzer Oil Company	Dhana	·
company: zinzer Oil Company	Pnone: 913-625-9448	i
Were: 7" casing set @ 3361' w/150 s	<u>xs. cmt. Perf. @ 2964' - 32</u>	<u>55'.</u>
Anhy. @ 1065' - C.I.B.P. @ 3320'. Per	<u>fs. @ 2964' - 3255'. Squeez</u>	e with_
300 sxs. 07-27-82: Holes in 7" casing	- 1626' to 2209'. Squeeze	<u> </u>
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze.	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs	•
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common.	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi	•
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze.	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi	•
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common.	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi	•
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common.	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi	•
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls.	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi	•
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi	*
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls.	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi	*
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent?	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[• • • • • • • • • • • • • • • • • • •
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[• • • • • • • • • • • • • • • • • • •
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M.	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year:	•
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400	•
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c	• x -] 94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c	• x -] 94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c	• x -] 94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c	• x -] 94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c	• x -] 94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c Job complete.	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface.	y - J 94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface.	y - J 94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c Job complete. Well TA'd with cement in casing at 168	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface.	y - J 94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c Job complete. Well TA'd with cement in casing at 168 Remarks:	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255'	y - J 94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c Job complete. Well TA'd with cement in casing at 168 Remarks: Condition of casing(in hole): GOOD X B	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255' AD Anhy.plug:YES X NO	• x -] 94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c Job complete. Well TA'd with cement in casing at 168 Remarks: Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255' ADAnhy.plug:YES X NO,NODakota plug:YES X	94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22, M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c Job complete. Well TA'd with cement in casing at 168 Remarks: Condition of casing(in hole): GOOD X B	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255' ADAnhy.plug:YES X NO,NODakota plug:YES X	94 sxs. asing. RECEIVED
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% qel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22 , M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c Job complete. Well TA'd with cement in casing at 168 Remarks: Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC Plugged through TUBING X , CASING	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth_September, Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255' ADAnhy.plug:YES_X_NO,NODakota plug:YES_X Elevation:G	94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22 , M. Actual plugging report: R.I.H. with town to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate complete. Well TA'd with cement in casing at 168 Remarks: Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC Plugged through TUBING X , CASING I did(X) Adid note Observe the p	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth_September, Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255' ADAnhy.plug:YES_X_NO,NODakota plug:YES_X Elevation:G	94 sxs. asing.
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22 , M. Actual plugging report: R.I.H. with town to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate complete. Well TA'd with cement in casing at 168 Remarks: Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC Plugged through TUBING X , CASING I did(X) Adid note Observe the p	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255' ADAnhy.plug:YES_X_NO,NODakota plug:YES_X_ Levation:G lugging. All.	PCANO RECEIVED RECEIVED AND RECEIVED AND COMMISSION PCANO PCANO
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22 , M. Actual plugging report: R.I.H. with town to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate complete. Well TA'd with cement in casing at 168 Remarks: Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC Plugged through TUBING X , CASING I did(X) Adid note Observe the p	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255' ADAnhy.plug:YES _X _NO,NODakota plug:YES _X Elevation:G lugging. AlmusHames	PCANO RECEIVED RECEIVED AND RECEIVED AND COMMISSION PCANO PCANO
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22 , M. Actual plugging report: R.I.H. with town to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate complete. Well TA'd with cement in casing at 168 Remarks: Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC Plugged through TUBING X , CASING I did(X) Adid note Observe the p	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255' ADAnhy.plug:YES_X_NO,NODakota plug:YES_X_ Levation:G lugging. All.	PECEIVED INO RECEIVED INO RECEIVED INO COMMISSION PROCESSION
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% gel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22 , M. Actual plugging report: R.I.H. with town to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate complete. Well TA'd with cement in casing at 168 Remarks: Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC Plugged through TUBING X , CASING I did(X) Adid note Observe the p	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255' ADAnhy.plug:YES _X _NO,NODakota plug:YES _X Elevation:G lugging. AlmusHames	P-2/5-P 3. 0.1994 KANSAS
300 sxs. 07-27-82: Holes in 7" casing 07-29-82 with 500 sxs. first squeeze. common. Third with 200 sxs. common. 8% qel with 1/4# F.C. plus 500# hulls. Plugging Proposal Received by: Dennis Plugging operations attended by agent? Completed: Hour: 12:15P.M., Day: 22 , M. Actual plugging report: R.I.H. with t cement to circulate at surface. Pulle Squeezed 75 sxs. cement to circulate c Job complete. Well TA'd with cement in casing at 168 Remarks: Condition of casing(in hole): GOOD X B Bottom plug(in place): YES X , CALC Plugged through TUBING X , CASING	- 1626' to 2209'. Squeeze Second squeeze with 200 sxs Ordered 575 sxs. 60/40 pozmi L. Hamel All[X], Part[], None[onth September , Year: ubing to 1650'. Spotted 400 d tubing. Hooked-up to 7" c ement up annulus to surface. 8' - 2209' and 2964' - 3255' ADAnhy.plug:YES _X _NO,NODakota plug:YES _X Elevation:G lugging. AlmusHames	PCANO RECEIVED RECEIVED AND RECEIVED AND COMMISSION PCANO PCANO