KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Layne Energy Operating, LLC	License Number: 33365
Operator Address: 1900 Shawnee Mission Parkway, Mission Woods, KS 66205	
Contact Person: Kimberlee Dixon	Phone Number: (620) 627 - 2499
Permit Number (API No. if applicable): 15-205-27856-0000	Lease Name & Well No.: Metzger 7L-34
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>NE _ SW _ NE _ NE _ </u>
☐ Settling Pit	Sec. 34 _Twp. 30S _R. 14
Workover Pit Haul-Off Pit	2145 Feet from North / South Line of Section
ان منظم المنظم المن المنظم المنظم	Feet from Fast / West Line of Section
	Wilson
Date of closure: October 20, 2010	
Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Self-Sealing Pit	
V	
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored.	RECEIVED NOV 2 9 2010 KCC WICHITA
Abandonment procedure of pit:	
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is Agent	NOV 2 9 2010 KCC WICHITA for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored.	NOV 2 9 2010 KCC WICHITA for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is Agent	NOV 2 9 2010 KCC WICHITA for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	NOV 2 9 2010 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	NOV 2 9 2010 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	NOV 2 9 2010 KCC WICHITA for Layne Energy Operating, LLC (Co.), best of his /her knowledge and belief.