STATE CORPORATION COMMISSION CONSÉRVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202		C NW NW , SEC. 12 , T 35 S, R 13 W/R	
		4620feet fro	
TECHNICIAN'S PLUGGING REPORT		4620 feet fro	m E section line
Operator	License / 5363	Lesse Nome Achenbach	Well # 2
Operator:	Berexco	CountyBarber	· · · · · · · · · · · · · · · · · · ·
Name& Address		Well Total Depth	
	Havs, KS 67601	Conductor Pipe: Size	feet
		Surface Casing: Size 8 5/	
Abandoned	Oli Well X Gas Well	Input Well SWD Well	D&A
	1 as hereinafter indicated		
Plugging	Contractor Clarke Corporation	on License N	5105 umber
	.O. Box 187, Medicine Lodge, KS		
	o plug at: Hour: 2 p.m. Day:		v 91
Plugging	proposal received from Jeff Clar	ke	<u> </u>
(company	name) Clarke Corporation	(ph	one) 316-886-5665
5 ¹ 2	" at 4911' w/100 sx cement, Per	fs at $4854-62$, squeezed $w/150$ s	ex cement, 4878-79
			
1st plug	sand back to 4825' and dump 5 s:	x cement on top of sand through	n bailer.
		50 sy cement 10 sy gel 100 l	
2nd plug	pump 300 lbs. hulls, 10 sx gel,	50 sx cement, 10 sx gel, 100 l	
2nd plug		50 sx cement, 10 sx gel, 100 l	lbs. hulls, releas
2nd plug	pump 300 lbs. hulls, 10 sx gel,	50 sx cement, 10 sx gel, 100 l	lbs. hulls, releas
2nd plug	pump 300 lbs. hulls, 10 sx gel,	50 sx cement, 10 sx gel, 100 l	Lbs. hulls, releas
2nd plug 8 5/8" w	pump 300 lbs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro	50 sx cement, 10 sx gel, 100 l . Possi Received by Steve I	Lbs. hulls, releas
2nd plug 8 5/8" w	pump 300 lbs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?:	50 sx cement, 10 sx gel, 100 l Posal Received by Steve I (TE All X Part	CHNICIAN)
2nd plug 8 5/8" w Plugging Operation	pump 300 lbs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?: as Completed: Hour: 3 p.m. Day:	posal Received by Steve I (TE All X Part 25 Month: 2	Char: 19
2nd plug 8 5/8" w Plugging Operation	pump 300 1bs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?: as Completed: Hour: 3 p.m. Day:	posal Received by Steve I (TE All X Part 25 Month: 2	Char: 19
2nd plug 8 5/8" w Plugging Operation	pump 300 lbs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?: as Completed: Hour: 3 p.m. Day:	posal Received by Steve I (TE All X Part 25 Month: 2	Char: 19
2nd plug 8 5/8" w Plugging Operation ACTUAL PL sand bri	pump 300 1bs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?: as Completed: Hour: 3 p.m. Day:	posal Received by Steve I All X Part 25 Month: 2 ack to 4825' and dumped 5 sx ce	Chnician) None Year: 19 Pferment on top of
2nd plug 8 5/8" w Plugging Operation ACTUAL PL sand bri 2nd plug	pump 300 lbs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?: Is Completed: Hour: 3 p.m. Day: UGGING REPORT 1st plug sanded bedge through bailer,	posal Received by Steve I (TE All X Part 25 Month: 2 ack to 4825' and dumped 5 sx ce with 300 lbs. hulls, 10 sx ge.	Pfeifer 8 1901 CHNICIAN) None Year: 19 ement on top of
2nd plug 8 5/8" w Plugging Operation ACTUAL PL sand bri 2nd plug 10 sx ge	pump 300 lbs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?: Is Completed: Hour: 3 p.m. Day: UGGING REPORT 1st plug sanded be dge through bailer, pumped down 8 5/8" surface pipe	possi Received by Steve I (TE All X Part 25 Month: 2 ack to 4825' and dumped 5 sx ce with 300 lbs. hulls, 10 sx gel 8" wiper plug and pumped 100 sx	Pfeifer 8 1901 CHNICIAN) None Year: 19 ement on top of
2nd plug 8 5/8" w Plugging Operation ACTUAL PL sand bri 2nd plug 10 sx ge	pump 300 1bs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?: Is Completed: Hour: 3 p.m. Day: UGGING REPORT 1st plug sanded be dge through bailer, pumped down 8 5/8" surface pipe	possi Received by Steve I (TE All X Part 25 Month: 2 ack to 4825' and dumped 5 sx ce with 300 lbs. hulls, 10 sx gel 8" wiper plug and pumped 100 sx	Pfeifer 8 1901 CHNICIAN) None Year: 19 ement on top of
2nd plug 8 5/8" w Plugging Operation ACTUAL PL sand bri 2nd plug 10 sx ge	pump 300 lbs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?: Is Completed: Hour: 3 p.m. Day: UGGING REPORT 1st plug sanded be dge through bailer, pumped down 8 5/8" surface pipe 1, 100 lbs. hulls, released 8 5/pressure 300 psi and shut in 250	posal Received by Steve I (TE All X Part 25 Month: 2 ack to 4825' and dumped 5 sx ce with 300 lbs. hulls, 10 sx gel 8" wiper plug and pumped 100 sx psi.	PFEIFER 8 1901 CHNICIAN) None Year: 19 ement on top of 1, 50 sx cement, x cement.
2nd plug 8 5/8" w Plugging Operation ACTUAL PL sand bri 2nd plug 10 sx ge Maximum	pump 300 1bs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent7: Is Completed: Hour: 3 p.m. Day: UGGING REPORT 1st plug sanded by dge through bailer, pumped down 8 5/8" surface pipe 1, 100 1bs. hulls, released 8 5/ pressure 300 psi and shut in 250 Used 60/40 Pozmix 6% gel by B.J.	possi Received by Steve I (TE All X Part 25 Month: 2 ack to 4825' and dumped 5 sx ce with 300 lbs. hulls, 10 sx ge. 8" wiper plug and pumped 100 sx psi. Services. Recovered 3000' of	Pfeifer 8 1901 CHNICIAN) None Year: 19 ement on top of t, 50 sx cement, x cement.
2nd plug 8 5/8" w Plugging Operation ACTUAL PL sand bri 2nd plug 10 sx ge Maximum Remarks:	pump 300 1bs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?: Is Completed: Hour: 3 p.m. Day: UGGING REPORT 1st plug sanded by dge through bailer, pumped down 8 5/8" surface pipe 1, 100 1bs. hulls, released 8 5/ pressure 300 psi and shut in 250 Used 60/40 Pozmix 6% gel by B.J. (If additional description 1	posal Received by Steve I (TE All X Part 25 Month: 2 ack to 4825' and dumped 5 sx ce with 300 lbs. hulls, 10 sx gel 8" wiper plug and pumped 100 sx psi.	Pfeifer 8 1901 CHNICIAN) None Year:19 1, 50 sx cement, x cement.
2nd plug 8 5/8" w Plugging Operation ACTUAL PL sand bri 2nd plug 10 sx ge Maximum Remarks:	pump 300 1bs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent7: Is Completed: Hour: 3 p.m. Day: UGGING REPORT 1st plug sanded by dge through bailer, pumped down 8 5/8" surface pipe 1, 100 1bs. hulls, released 8 5/ pressure 300 psi and shut in 250 Used 60/40 Pozmix 6% gel by B.J.	possi Received by Steve I (TE All X Part 25 Month: 2 ack to 4825' and dumped 5 sx ce with 300 lbs. hulls, 10 sx ge. 8" wiper plug and pumped 100 sx psi. Services. Recovered 3000' of	Pfeifer 8 1901 CHNICIAN) None Year:19 ement on top of to care, k cement.
2nd plug 8 5/8" w Plugging Operation ACTUAL PL sand bri 2nd plug 10 sx ge Maximum Remarks:	pump 300 1bs. hulls, 10 sx gel, riper plug and pump 100 sx cement Plugging Pro Operations attended by Agent?: Is Completed: Hour: 3 p.m. Day: UGGING REPORT 1st plug sanded by dge through bailer, pumped down 8 5/8" surface pipe 1, 100 1bs. hulls, released 8 5/2 pressure 300 psi and shut in 250 Used 60/40 Pozmix 6% gel by B.J. (If additional description is plugging.	possi Received by Steve I (TE All X Part 25 Month: 2 ack to 4825' and dumped 5 sx ce with 300 lbs. hulls, 10 sx ge. 8" wiper plug and pumped 100 sx psi. Services. Recovered 3000' of	Pfeifer 8 1901 CHNICIAN) None Year: 19 ement on top of t, 50 sx cement, x cement.