KANSAS STATE CORPORATION COMMISSION

RECEIVED
STATE CORPORATION COMMISSION CONSERVATION DIVISION AGENT'S REPORT

1. P. Roberts Assistant Director 500 Insurance Building 212 North Market Wichita 24 Kansas MAY 16 1962 OS-16-62 CONSERVATION DIVISION Wichita, Kansas

wichita 2, Kansas
File NoCounty:
Location: CNW SE SW Sec. 21 Twp. 11 Rge. (E) (W) 17
Name of Fleld:Total Depth:3960
I have this date completed supervision of plugging of:
Lease Name: Bemis Well No. C-5
Operator's Full Name: Ryan Consolidated Pet
Complete Address: 3400 Republic Natl Bk Bldg Dallas, Texas
Plugging Contractor Halliburton Cementing Co
Address: Hays, Kansas License No.
Oll Well Gas Well Input Well SWD Well X D. & A
Other well as hereafter indicated:
Was any delay in plugging operations caused by Conservation Division Agent?
Yes No x
If yes how long?Reason:
Operation Completed: Hour 12 Noon Day 12 Month 5 Year 62
The above well was plugged as follows: 10 3/4" 1139' circulated with cement - 7" 3415' with 125 sax cement behind
4½" line cemented in 3383' to 3664' - circulated hole with heavy gel mud
through 2" tubing at 625' (40 sax Gel) - publed 2" to 325', pumped 150
sax cement through 2" at 325' filling hole to 0' with cement and circulate
7" to 0'.
Mudding and cementing by Halliburton Co.
Signed: Conservation Division Agent
Reviewed: Harold Hollis Field Supervisor

Remarks:

INVOICED DATE 5/18/62 INV. NO. 4999-W