

KANSAS CORPORATION COMMISSION  
OIL & GAS CONSERVATION DIVISION

Form GDP-4  
April 2004  
Form must be Typed

CLOSURE OF SURFACE PIT

07

Operator Name: JOHN O. FARMER, INC.	License Number: 5135
Operator Address: P.O. Box 352 Russell, KS 67665	
Contact Person: Marge Schulte	Phone Number: ( 785 ) 483 - 3145, Ext. 214
Permit Number (API No. if applicable): 167-23,418-00-00	Lease Name & Well No.: DIETZ # 1
Type of Pit: <input type="checkbox"/> Emergency Pit <input type="checkbox"/> Burn Pit <input type="checkbox"/> Settling Pit <input checked="" type="checkbox"/> Drilling Pit <input type="checkbox"/> Workover Pit <input type="checkbox"/> Haul-Off Pit	Pit Location (QQQQ): 20'N & 70'E of _____ - SW - SW - NW Sec. 18 Twp. 14S R. 14W <input type="checkbox"/> East <input checked="" type="checkbox"/> West 2290 Feet from <input checked="" type="checkbox"/> North / <input type="checkbox"/> South Line of Section 400 Feet from <input type="checkbox"/> East / <input checked="" type="checkbox"/> West Line of Section Russell _____ County

Date of closure: 8-14-07

Was an artificial liner used?  Yes  No

If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  
 Sealed with clay soil, native and fresh mud.

RECEIVED  
KANSAS CORPORATION COMMISSION  
**AUG 29 2007**  
CONSERVATION DIVISION  
WICHITA, KS


Abandonment procedure of pit:  
 Allow liquid contents to evaporate, let cuttings dry and backfill.

The undersigned hereby certifies that he / she is \_\_\_\_\_ president \_\_\_\_\_ for John O. Farmer, Inc. (Co.), a duly authorized agent, that all information shown hereon is true and correct to the best of his / her knowledge and belief.

*John O. Farmer III*  
 Signature of Applicant or Agent

Subscribed and sworn to me on this 27th day of August, 2007

*Margaret A. Schulte*  
 Notary Public



My Commission Expires: