KANSAS
STATE CORPORATION COMMISSION

## CONSERVATION DIVISION AGENT'S REPORT

TO: Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2, Kansas

File No.		County:	E	lis	<del> </del>		·····	<del></del> ,	
Location:	NE SW SE		_Sec23	Twp	11	_Rge.	17	(E)_	(W)
Name of Field	l: Bemis			Total	Depth	:	3443	<del></del>	
I have this o	late completed sup	pervision of	f plugging	of:					
Lease Name:	Rumsey				Wel	1 No.	<del></del>	8	<del></del>
Operator's Fu	111 Name: C	ities Ser	vice Pet	Co				<del></del>	
Complete Adda	cess: B	ox 533 R	ussell, I	Cansas	······································				
Plugging Cont	tractor: C	. E. Shul	1						
Address:	G	reat Bend	, Kansas		Lic	ense	No	8	· · · · · · · · · · · · · · · · · · ·
Oil Well x	Gas Well	Inpu	t Well	swi	Well_	· · · · · · · · · · · · · · · · · · ·	D	& A	
Other well as	hereafter indica	ated:						· · · · · · · · · · · · · · · · · · ·	<del></del>
Was any delay	in plugging oper	rations cau	sed by Con	servation	Divis	ion A	gent?	Yes	Nox
If yes how 1	ong?		Reason	:					
The above wel	npleted: Hour	follows:		<del></del>		2 wit			ar 61
Filled wit	h sand to 3400	', set 4	sax cemer	nt with	dump	bail	er, p	ulled	24501
5ੈਵਾਂ to 425	', circulated	hole with	heavy mu	ıd thr <b>p</b> u	igh 5쿨	" at	425	( 18	sax Ge
displaced	20 sax cement	through 5	ā" at 425	, heav	y mud	to	160',	disp	laced
20 sax cem	ent through $5\frac{1}{2}$	" at 160'	, heavy n	nud to 3	55', s	et b	ridge	and	10 sax
cement to	bottom cellar.				¥				
Mudding and	cementing by	Halliburt	on Co.						
<u> </u>		)_ /	Signed		onserva	tion	Divisi	on Age	nt
Reviewed:	yall-(0-1/4) Field Supervi	Isor	<del></del>			·E)	AE		·
Remarks:	ı				· ·	, a	 (.)	<b>^</b> ;	
(	1 i1 V (	DICEC	)	, [		1.1 Marianta 11.1 12 cm - 4		· ·	