STATE OF RANSAS				15-	1051-6	0512 00			
Tve All diformation Completely	WELL PLUGGING RECORD								
Nikke Required Affidavit Mail or Deliver Report to:		VV 1	CLL PLU	GGING R	LCURD				
Conservation Division State Corporation Commission				4	•	,			
800 Bitting Building	•	ELLIS	Cour	nty Sec 15	Twn 13 Rge	(E) 20 (W)			
Wichita, Kansas									
NORTH	Location as "NE/CNW4SW4" or footage from lines SW, SW, SE Lease Owner JONES, SHELBURNE & FARMER, INC.								
	Lease Name NIERNBERGER Well No. 1								
	Office Address RUSSELL, KANSAS Character of Well (completed as Oil, Gas or Dry Hole) DRY HOLE								
	Date well comple	eted	1/13	/50 19					
	Application for a	olugging filed		••••••••••	1/13/	/50 19			
	Application for n	dugging annrov	ed		1/13	/50 19			
	Plugging comme	nced			1/13/	/50 19			
i lii	Plugging comme	had		••••••••	1/13	/50 10			
	Pagging complete	donment of we	di or producir	or formation	1/13/50 19				
	neason for aban					ζ			
	Tf a maduaina w					SD 19			
	-					e plugging was com			
Locate well correctly on above	•				_	e prugging was com			
Section Plat Jame of Conservation Agent who superv	menced?			D FIDAN DE	AlπbΔ.				
ame of Conservation Agent who superv	rised plugging of this	well		ulalilasimi		.u 20164 T			
roducing formationNONE			Botto	m	total Depth of W	ell J.71203 r ee			
how depth and thickness of all water, o	il and gas formation	s.							
OIL, GAS OR WATER RECORDS					C	ASING RECORD			
					<u> </u>	D. 1.0.			
Formation	Content	From	То	Size	Put In	Pulled Out			
A 200 20 10220 1									
Gemented with 12	O sacks.			8 5/8"	1881	None			
				,					
				ľ	1 1				
Describe in detail the manner in watroducing it into the hole. If cement feet for each plug s	or other plugs were								
7 11-7 0177 3			::						
l. Hole filled w	Tru neavy mid								
2. Halliburton p	lug spotted s	t 1951.				······································			
3. Fifteen sacks	,			·····	· · · · · · · · · · · · · · · · ·				
y a seriore a accumulation of				• • • •					
4. Hole filled t	o within 20 f	eet of to		avy mud.		·			
5. Halliburton p	lug spotted s	t 20 feet							
6. Fifteen sacks	cement mixed	and hole	filled t	o ton with	game.				
				77					
					.!	<i>T</i>			
<u> </u>									
				ار ۸۰	(00-0				
		••••••		O[~	18-1950				
	(If additional d	lescription is necess	ary, use BACK o	f this sheet)					

JONES, SHELBURNE & FARMER, INC. Correspondence regarding this well should be addressed to..... RUSSELL, KANSAS COUNTY OF RUSSELL STATE OF KANSAS John Q. Farmer (employee of owner) or (owner or operator) of the above-described well,


being first duly sworn on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filed and that the same are true and correct. So help me/God described well as filed and that the same are true and correct. So help me/God) (Signature)....

RUSSELL, KANSAS (Address)

.....day of...

June 3, 1953

4-49—10M



Jones, Shelburne & Farmer, Inc.

Russell, Kansas

15-051-00512-00-00

CONTRACTOR'S VERIFIED LOG

lool-NT	whereas a factorise	The second of the second of	PLITO	CA. PANOLO
oor name		County	<u> </u>	_ StateKANSAS
ommencem	ent Date	January 2, 1950 Co		January 13, 1950
*		Log of W	7è11.	
, De	pth	<u></u> 3	Deviation	
From	То	Formation	from vertical (degre	Rémarks
	3000	Aliana		
1020	1020 1125	Shale and Shells		
1125			A may a management of the same	
1250	1550	Red Beds		
1550 1590	1590	Anhydrite	المراق في الأسليون المراجعة المستراك المراق ا المراقعة المراقعة ال	A supplied to the second of th
1930	1930 cm 2050	Shale and Shells Shale and Salt	ALCOUNTY OF SEATE	L'affic
2050 🔞	2100	Shale and Shells		
2100	3560	lime and Shale	e a cesa e de esta de la cesa e de esta e	e ilgge have seen entre en e en
3560 3860	3860 3881	Iime Cherty Conglomerate		A CONTRACTOR OF THE CONTRACTOR
3881	3918	Idme		·
	3918	Total Depth		
		TOPS:		
1	1	<u>-</u>		-
		1550 Anhydrite		
		3466 Heebner 3481 Toronto		
		3508 Konsas City Top		e view
		3758 Kansas City Base		
]	3850 Conglomerate		
	·	3881 Arbuckle		
	. <u> </u>			
	ŀ			
	•	- 1		
ľ	•	DRY AND ABANDONED		
	-			
ļ				
		4		
		to the second		and the second
	1		JAN 1	1 & 1950
مسوم یے ۔۔			Similar	
			(C), []	- John on
j			" Keni	Sil
	į.		1-	18-1960
1				100
1			.	5
	5.9	PLUGGING	PERSONAL STATE	

Depth		Formation		Deviation from vertical (degrees	Remarks		
From	То	2 01111041011		vertical (degrees)) Itematks		
		The second secon		·	· •		
	· · ·		r - Na maraka ya marayayayayaya				
·							
	·		44				
	•						
					سان ن ن ن ن ن ن ن ن ن ن ن ن ن ن ن ن ن ن		
,							
* .					Total Depth 39182		
Was well to b	e deepened b	y another Contractor?	:	- Age	37402		
Ψ* .		SING LEFT IN HOLE AFTER CO	MPLETION	OR ABANDON	MENT		
		*		FOOTAGE			
Size Wt.	Grade I	Range Thread Delivered	Run	Set At Unu	sed Pulled Left in Hole		

	D.		¥.	4.			FOO	TAGE		
Size	Wt.	Grade	Range	Thread	Delivered	Run	Set At	Unused	Pulled	Left in Hole
	. eg in		The state of the s	. •			1			
8 5/8	:		Comented	with 120	sacks		1881		None	188*
7,0	177 J	*					1	2		
APPENDING TO STREET		-		Hamilton and the second second	a paramental traperty at a		Territorian successive		Andrewski Consission	Company of the Compan
I.J.	and the state of the	-	3	مِفَةً	an ^{the} site a t		1 649 (1 15) 1 105	148 M x 2 1	ŢŅ.	1 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
	£26∑4		i i					· 48		
mante de anti-métro	nskapen = u	Compression and the Compression of the Compression	participation (and highwater)	. 	A1			C 75		
					276 or .72	115				

This ericalization Cates	
Deviation From Vertical Data is Correct as Shown	The foregoing Well Log and other data are correct.
Company Superintendent	JONES, SHELBURNE & FARMER, Inc.
(This space for Company use)	By Mohwo. Farmer
CLAVOR	ns yanara dan kanara sa