Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-5 August 2008 Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: John O. Farmer, Inc.	License Number: 5135
Operator Address: P.O. Box 352, Russell, KS 67665	
Contact Person: Marge Schulte	Phone Number: (785) 483 - 3145, Ext. 214
Permit Number (API No. if applicable): 15-167-00,167-00-00	Lease Name: Kejr "C"
Source of Waste: Dike Emergency Pit Settling Pit Workover Pit Drilling Pit Burn Pit Haul-off Pit Steel Pit Spill / Escape	Well Number: #1 Source Location (QQQQ): SW _ SE Sec
Type of waste to be disposed:	Other:
Amount of waste:5 No. of loads400_ Barrels	YDS ´
Destination of waste: Reserve Pit Haul Off Pit 🗸 Disposal Well Lease Road Dike / Berm Other:	
If waste is transferred to another reserve pit, is the lease active?	
Location of waste disposal: Operator Name: John O. Farmer, Inc. Lease Name: Kejr "B" Docket No./API No.: E-27,314 Comments:	Date of Waste Transfer: 1-25-11 License No.: 5135 Sec. 14 Twp. 15S R. 13 ☐ East
	RECEIVED FEB 1 8 2011 KCC WICHITA
The undersigned herby certifies that fie/she is	