Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD

Form CP-4 March 2009 Type or Print on this Form Form must be Signed rust be Filled

OPERATOR: License #: 4058				API NO. 15-033-0028-00-02		
OPERATOR: License #: 4058 Name:American Warrior				Spot Description: C-NE-NE-SW		
Address 1: P.O Box 399				C_NE_NE_SW Sec. 17 Twp. 33 S. R. 18 East West		
Address 2:				2,319 Feet from North / South Line of Section		
City: Garden City State: KS				2,335 Feet from East / West Line of Section		
Contact Person:Kevin Wiles				Footages Calculated from Nearest Outside Section Corner:		
Phone: (620_) 275-2963				☐ NE ☐ NW ☐ SE 🗸 SW		
Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic				County: Comanche		
Water Supply Well ☐ Other: ☐ SWD Permit #: ☐ Cas Storage Permit #: ☐ Cas Stor				Lease Name: Hackney Well #: #1 SWD		
ENHR Permit #: Gas Storage Permit #: Is ACO-1 filed? ✓ Yes No If not, is well log attached? ✓ Yes ✓ No				Date Well Completed: 8/18/1966		
Producing Formation(s): List All (if needed attach another sheet)				The plugging proposal was approved on: 4/22/2010 (Date) by: Richard Lacey (KCC District Agent's Name)		
Depth to Top: <u>4842</u> Bottom: <u>4851</u> T.D. <u>6225</u>						
Depth to Top: T.D				Plugging Commenced: 04/22/2010 Plugging Completed: 04/27/2010		
Depth to Top: Bottom:T.D				Plugging Completed: U4/2//2010		
Show depth and thickness of all water, oil and gas formations.						
Oil, Gas or Water R				Record (Surfa	ce, Conductor & Produc	
Formation	Content	Casing	Size		Setting Depth	Pulled Out
		Conductor	13 3/8	3	261	None
		Surface	8 5/8		2667	None
		Production	5 1/2		5245	3500
Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set. Set CIBP at 4680', 2sx cement on CIBP, cut casing at 3500', lay down, run tubing to 1st 990', pump 20 sx gel, 50sx 60/40 poz 2% gel, 2nd 290', 50sx 60/40 poz, 3rd 60', 20sx 60/40 poz, circulate to surface						
5/11 - Measure down surface, cement at 20', measure conductor, cement down 6', back fill cellar						
						RECEIVED
						MAY 1 7 2010
Plugging Contractor License #: 5105			Name: _	Clarke	Corporation	KCC WICHITA
Address 1: _P.O. Box 187			Address	2:107 \	N. Fowler	
City: _Medicine Lodge				State: Ka	nsas	zip: <u>67104</u> +
Phone: (620) 886-5665						
Name of Party Responsible for P	Plugging Fees: <u>Ameri</u>	ican Warrior				
State of Kansas County, Barber				, SS.		
Mark Morgenstern				_ Demployee of Operator or Department on above-described well,		
(Print Name) being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and						
the same are true and correct, so help me God.						
Signature: 7 Mark Magenalen						