

15169-00039-0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Doley Oil Company Address Hays, Kansas
(Applicant)

Lease (Farm Name) Olga Schrader Well No. 1

Well Location SW SW NE Sec. 7 Twp. 15 Rge. 4 (X)-(W)

County Saline Field Name (if any) _____

Total Depth 3835 feet Oil Gas Dry Hole X

Was well log filed with application? yes if not, explain: _____

Date and hour plugging is desired to begin 11-1-54 10:00 P.M.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Ernest J. Doley Address Hays, Kansas

Plugging Contractor Kiefer & Krause Drilling Co., Inc.

Plugging Contractor's License No. _____

Address Post Office Box 396, Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to **RECEIVED**
Doley Oil Company Address Box 473, Hays, Kansas STATE CORPORATION COMMISSION

Doley Oil Company Address Box 473, Hays, Kansas NOV - 6 1954
11-6-54

and payment will be guaranteed by applicant. CONSERVATION DIVISION
Wichita, Kansas

Richard B. Krause
Applicant or Acting Agent
for Kiefer & Krause Drilling Co., Inc.
Date November 1, 1954

PLUGGING
FILE SEC 7 T 15 R 4W
BOOK PAGE 75 LINE 6



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
~~RECEIVED IN THE SUBSIDIARY~~
 WICHITA, KANSAS

November 3, 1954

211 N. Broadway

Well No.	1
Lease	Schrader
Description	SW SW NE 7-15-11W
County	Saline
File No.	75-6

Doley Oil Company
 1109 Main
 Hays, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. River, Box B, Pratt, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

BY: J. P. Roberts
 J. P. ROBERTS

cc: District Plugging Supervisor