Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-5 August 2008 Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: John O. Farmer, Inc.	License Number: 5135
Operator Address: P.O. Box 352, Russell, KS 67665	
Contact Person: Marge Schulte	Phone Number: (785) 483 - 3145, Ext. 214
Permit Number (API No. if applicable): 15-159-02,327 - 000	Lease Name: Hoops "B"
Source of Waste: Dike Emergency Pit Settling Pit Drilling Pit Burn Pit Haul-off Pit Steel Pit Spill / Escape Type of waste to be disposed: Fluid Soil Mud / Cuttings	Well Number: #4 Source Location (QQQQ): E2 _ W2 _ NE Sec. 8 Twp. 19S R. 10 East ✓ West 1,320 Feet from ✓ North / ☐ South Line of Section 1,650 Feet from ✓ East / ☐ West Line of Section Rice County
Amount of waste: 2-1/2 No. of loads 190 total Barrels	TonsYDS
Destination of waste: Reserve Pit Haul Off Pit Disposal Well Lease Road Dike / Berm Other:	
If waste is transferred to another reserve pit, is the lease active? Yes No	
Location of waste disposal: Operator Name: John O. Farmer, Inc. Lease Name: Hoops "B" #7 SWD Docket No./API No.: D-19,462 ** Comments:	Date of Waste Transfer: 7-7-11 License No.: 5135 Sec. 8 Twp. 19S R. 10 East West Rice
The undersigned herby certifies that he she is	