## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-5 August 2008
Form must be Typed

## **EXPLORATION & PRODUCTION WASTE TRANSFER**

Operator Name: Terry E. Morris d/b/a GLM Company	License Number: 3134
Operator Address: P.O. Box 193 Russell, Kansas 67665	
Contact Person: Terry E. Morris	Phone Number: ( 785 ) 483 - 1307
Permit Number (API No. if applicable): 15-167-22665 - ()()()	Lease Name: Brown "B"
Source of Waste:  Dike  Emergency Pit Settling Pit  Workover Pit Drilling Pit  Burn Pit Haul-off Pit Steel Pit Spill / Escape  Type of waste to be disposed:	Well Number: #3  Source Location (QQQQ):CN/2 NE  Sec. 31Twp. 13R. 14East
Amount of waste: No. of loads 80 Barrels	YDS
Destination of waste: Reserve Pit Haul Off Pit 📝 Disposal Well Lease Road Dike / Berm Other	
If waste is transferred to another reserve pit, is the lease active?	
Location of waste disposal: Operator Name: Terry E. Morris d/b/a GLM Company Lease Name: Boxberger "A"  Docket No./API No.: E07619.2 15-167-90373-00-00  Comments:	Date of Waste Transfer: 08/25/2010  License No.: 3134  Sec. 26 Twp. 14 R. 14 East West  County: Russell
The undersigned herby certifies that (he) she is	

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

JUN 2 1 2011 KCC WICHITA