4-061012

12 - 7 тο: API Number: 15-199-20, 243 -60-00 STATE CORPORATION COMMISSION C NW SE /4 SEC. 32 , 15 S, 41 W CONSERVATION DIVISION - PLUGGING 130 SOUTH MARKET, SUITE 2078 1980 feet from S section line WICHITA, KANSAS 67202 1980 feet from E section line Lease Kuder Well # 1 Operator license# 8541 County: Wallace /69.97 Operator: Petex, Inc. Well total depth______ feet Address: 1610 E. Sunshine Springfield, MO 65804 Conductor Pipe: 0 inch @ 0 feet Surface pipe 8 5/8 Inch @ 339 feet Aband. oil well , Gas well , Input well , SWD , D & A X , Plugging contractor: Murfin Drilling Company, Inc. License# -Address: Wichita, Kansas 67202 Company to plug at: Hour: 5:00 A.M. Day: 9 Month: December Year: 1996 Plugging proposal received from: ______ Jim Renner Company: Murfin Drilling Company, Inc. Phone:____ Were: Order 200 sxs 60/40 posmix - 6% gel with 1/4# floseal per sack. Space all plugs with heavy drilling mud through drill pipe. Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 7:00 A.M. , Day: 9 , Month: December , Year: 1996 Actual plugging report: 1st. Plug at 2730' w/25 sxs. Anhydrite 2714' - 2740'. 2nd. Plug at 1725' w/100 sxs. Dakota 1425' - 1725'. 3rd. Plug at 390' w/40 sxs. Surface pipe to 339'. 4th. Plug at 40' w/10 sxs. Rathole with 15 sxs. Mousehole with 10 sxs. Remarks: Allied Cementing. Condition of casing(in hole): GOOD X BAD_____ Anhy.plug: YES X NO___ Dakota plug: YES X , NO____ Bottom plug(in place): YES___, CALC__, NO_X Plugged through TUBING_____, CASING___. Elevation:_____3775 I data ($\sqrt{1}$) A fld not \times] observe the plugging. (agent) Form CP-2/3