		N02	RECORD 3-117		ABER <mark>1507/-</mark> NAME GUM	20,420-00-	
	TYPE OR PRINT NOTICE: Fill out completely and return to Cons. Div. office within 30 days.			• <u>4620</u>	WELL NUMBER 1 4620 Ft. from S Section Line 660 Ft. from E Section Line		
LEASE OPERATOR National Coop.	. Refinery As	soc.					
ADDRESS P.O. Box 6, Great Bend, KS 67530					COUNTY Greeley		
PHONE#()OPERATORS LICENSE NO.					il Completed		
Character of Well D&A					g Commenced _		
(Oil, Gas, D&A, SWD, Input, Water Supply Well)				Pluggin	g Completed _	03-29-86	
Did you notify the KCC/KDHE Joi	int District	Office	prior to	plugging	this well?_	Yes	
Which KCC/KDHE Joint Office did	d you notify?	Mr	Lacy, (Garden City	, KS		
s ACO-1 filed?If	not, is well	log a	ittached?				
Producing Formation							
how depth and thickness of all	l water, oil	and ga		ions. Casing Reco	RD.		
	From	То	Size	Put in	Pulled outsta	TE CORPORATION CO.	
	From		Size 8-5/8"	320 T	Pulled outSTA	TE CORPORATION COMMIT	
Formation Content Surface	From	То		Į		13 19RG	
Surface escribe in detail the man'ner i	in which the	well w	8-5/8"	3201	ing where the	ONSERVATION DIVISION Wichida, Kanada	
Surface Describe in detail the manner is laced and the method or method are used, state the character 1st pluq @ 2775' w/50 sx 2nd plug @ 2000' w/80 sx, 3rd plug @ 505' w/30 sx 4th plug @ 40' w/10 sx	in which the ds used in in of same and 5 sx in ra	well w troduc depth uthole	8-5/8" as plugge ing it in placed, f	320' ed, indicate to the hole from feet	ing where the e. If cement tofeet eac	ONSERVATION DIVISION MICHAEL FRANKS WAS	
Surface Describe in detail the manner is laced and the method or method ere used, state the character 1st pluq @ 2775' w/50 sx 2nd plug @ 2000' w/80 sx, 3rd plug @ 505' w/30 sx 4th pluq @ 40' w/10 sx (If additional descri	in which the ds used in in of same and 5 sx in ra 5 sx in mo	well w troduc depth thole usehol	8-5/8" as plugge ing it in placed, f	320' ed, indicate to the holicom_feet	ing where the e. If cement tofeet eac form.)	ONSERVATION DIVISION MUCHICA, FRANKS WAS	
Surface Describe in detail the manner is laced and the method or method are used, state the character 1st pluq @ 2775' w/50 sx 2nd plug @ 2000' w/80 sx, 3rd plug @ 505' w/30 sx 4th plug @ 40' w/10 sx	in which the ds used in in of same and 5 sx in mo	well w troduc depth uthole usehol	8-5/8" as plugge ing it in placed, f	320' ed, indicate to the holicom_feet	ing where the e. If cement tofeet eac	ONSERVATION DIVISION MUCHIA FPRAIS WAS OR other plugh h set.	
Surface Describe in detail the manner is placed and the method or method ere used, state the character 1st pluq @ 2775' w/50 sx 2nd plug @ 2000' w/80 sx, 3rd plug @ 505' w/30 sx 4th plug @ 40' w/10 sx (If additional describes of Plugging Contractor Months of Plugging Contractor Suite 1985 (Sinter Surface Plugging Contractor Suite 1985)	in which the ds used in in of same and 5 sx in mo	well w troduc depth athole cessar ng Com ta, KS	8-5/8" as plugge ing it in placed, f	320' ed, indicate to the holicom_feet	ing where the e. If cement tofeet eac form.)	ONSERVATION DIVISION MUCHIA FPRAIS WAS OR other plugh h set.	

(Signature)

(Address)

SWORN TO before me this _

11-18-87

Robert A. Ramseyer 250 N. Water, Su/

> Notary Public Rhonda R. Hudson

lst Michita, KS

the same are true and correct, so help me God.

RHONDA R. HUDSONND NOTARY PUBLIC STATE OF KANSAS My Appt. Exp.

My Commission Expires: