TO:

STATE CORPORATION COMMISSION **CONSERVATION DIVISION - PLUGGING**

130 SOUTH MARKET, SUITE 2078 **WICHITA, KANSAS 67202**

API Well Number: 15-153-20821-00-00

Spot: S2S2SW

Sec/Twnshp/Rge: 31-5S-36W

330 feet from S Section Line,

1470 feet from W Section Line

Lease Name: TOVREA

Well #: 2

County: RAWLINS

Total Vertical Depth: 5005 feet

Operator License No.: 6509

Op Name: CLARK, JIM D. DBA CLA-MAR OIL, CO

Address: PO BOX 1197

HAYS, KS 67601

Depth (ft) Pulled (ft) Comments String Size SURF 8.625 419 285 SX

T1 2.375 5036 **PKR** 4434

PROD 5.5 4995

175 SX

Perfs:

Тор

4535

4464

4392

4540

4468

4398

Well Type: OIL

UIC Docket No:

Date/Time to Plug: 09/13/2011 9:00 AM

Bot Thru Comments

Plug Co. License No.: 6426

Plug Co. Name: EXPRESS WELL SERVICE & SUPPLY INC

Company: CLA-MAR OIL, COMPANY

Phone: (785) 623-1700

Plugging

Proposed Ordered 350 sxs 60/40 pozmix - 4% gel - 300# hulls.

Method:

Plug through tubing.

Proposal Revd. from: JIM CLARK

Plugging Proposal Received By: CASE MORRIS Date/Time Plugging Completed: 09/13/2011 5:00 PM WitnessType: COMPLETE (100%)

KCC Agent: DARREL DIPMAN

Actual Plugging Report:

8 5/8" surface casing set at 419' w/285 sxs cement.

5 1/2" production casing set at 4995' w/175 sxs cement.

Perforations from 4558' - 4562' - squeezed with 150 sxs cement.

TD 5005'.

09/13/2011 - Tubing sanded in 5 1/2" casing from 4348' to TD.

Backed off tubing at 4348' - pumped 15 sxs cement.

Pulled tubing to 3125'. Perforated 5 1/2" casing with strip jet - pumped 25 sxs cement mixed with 100# hulls.

Pulled tubing to 2325'. Perforated 5 1/2" casing with strip jet - pumped 25 barrels fresh water followed with 235 sxs cement mixed with 150# hulls.

5 1/2" production casing developed leak inside of 8 5/8" surface casing.

Pulled tubing to 1000' - pumped 75 sxs cement.

Cement to surface from 5 1/2" production casing.

Shut circulation valve forcing cement into surface casing - pumped remainder of cement.

ALLIED CEMENTING COMPANY-TICKET #38282.

8 5/8" had strong blow but cement did not circulate.

Pulled tubing to surface.

8 5/8" surface casing and 5 1/2" production casing equalized and will be topped at later time.

RECEIVED

SEP 1 9 2011

KCC WICHITA

Remarks:

Plugged through: TBG

Signed Harrel Lypman

(TECHNICIAN)

District: 04