**Notice:** Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

## Kansas Corporation Commission Oil & Gas Conservation Division

## Form CP-4 March 2009 Type or Print on this Form Form must be Signed All blanks must be Filled

## WELL PLUGGING RECORD K.A.R. 82-3-117

OPERATOR: License #: 34318				API No. 15 - 15 . 065 . 01376 . 00 . 00				
Name: Berexco, L.L.C.				Spot Description:				
Address 1: P. O. Box 723				N/2 - SW - NW Sec. 14 Twp. 9 _ S. R. 21 East  West				
Address 2: 2020 N Bramblewood, Wichita KS 67201				1,650 36 30 Feet from Worth South Line of Section				
City: <u>Hays</u> State: <u>KS</u> Zip: <u>67601</u> +				3,630 Feet from (Fast)/ West Line of Section				
Contact Person:Dennis Kirmer					Footages Calculated from Nearest Outside Section Corner:			
Phone: (785_) 628-6101					NE NW SE SW			
Type of Well: (Check one) Oil Well Gas Well GG D&A Cathodic				County:	Graham			
Water Supply Well Other: SWD Permit #:							#: _3	
ENHR Permit #: Gas Storage Permit #:				Date Well Completed: 9/1948				
Is ACO-1 filed? Yes No If not, is well log attached? Yes No.							(Date)	
Producing Formation(s): List All (If needed attach another sheet)  -L-KC				by:(KCC District Agent's Name)				
ARB Depth to Top: 3699 Bottom: 3705 T.D. 3705				Plugging Commenced: 10-7-11				
Depth to Top: Bottom: T.D				Plugging Completed: 10-7-11				
Dotton. I.b.								
Show depth and thickness of all water, oil and gas formations.								
Oil, Gas or Water Records Casing F				Record (Surface, Conductor & Production)				
Formation	Content	Casing	Size		Setting Depth	Pulled Out		
L-KC	Oil/Water	Surface	8 5/8		200'	0		
Arbuckle	Oil/Water	Production	5 1/2		3699	0		
Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.  Rig up Perf Tech. Shoot 2 holes each at 2250', 1720', 1000'. Run tubing to 3000'. Rig up Allied Cementing. Mix 100 sks 60/40 poz 4% gel w/300# hulls. Pull tubing to 2000'. Mix 100 sks cement w/200# hulls. Pull tubing to 1000'. Circulate cement to surface in 5 1/2 and 8 5/8 casing. Pull tubing out of hole. Top off 5 1/2 and 8 5/8 casing. Well plugged 1:30 P.M. Witness by Pat Bedore-Hays KCC.								
Plugging Contractor License #: 34318				Name: Berexco, L.L.C.				
Address 1: P. O. Box 723				ddress 2: 2020 N Bramblewood, Wichita KS 67201				
City: _Hays				State: KS zip: <u>67601</u> +				
Phone: (785) 628-6101								
Name of Party Responsible for Plugging Fees: Berexco, L.L.C.								
State of Kansas County, Sedgwick				_, \$S.				
Dennis Kirmer (Print Name)				Employee of Operator or Operator on above-described well,				
being first duly sworn on oath,	,	ge of the facts statements, ar	d matter	s herein con	tained, and the log of	the above-describe	ed well is as filed, and	
the same are true and correct, so help me God.  RECEIVED								
Signature: Wenn	is Kuney						CT 13 2011	