KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Murfin Drilling Company, Inc.	License Number: 30606
Operator Address: 250 N. Water, Suite 300, Wichita, KS 67202	
Contact Person: John Gerstner	Phone Number: (785) 421 - 2103
Permit Number (API No. if applicable): 15-195-22657	Lease Name & Well No.: Nimz #1-13
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NE _ SE _ NW _ SW
Settling Pit	Sec. 13 Twp. 12S R. 24 East West
Workover Pit Haul-Off Pit	1800 Feet from North / ✓ South Line of Section
	1180 Feet from East / West Line of Section
	Trego County
Date of closure: 5/23/11 Was an artificial liner used? ☐ Yes	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Desillia	
Drilling mud.	RECEIVED
Drilling mud.	RECEIVED JUN 0 2 2011
Abandonment procedure of pit:	JUN 0 2 2011
Abandonment procedure of pit:	JUN 0 2 2011
Abandonment procedure of pit:	JUN 0 2 2011
Abandonment procedure of pit: Let dry & backfilled pit.	JUN 0 2 2011 KCC WICHITA
Abandonment procedure of pit: Let dry & backfilled pit.	JUN 0 2 2011 KCC WICHITA for
Abandonment procedure of pit: Let dry & backfilled pit. The undersigned hereby certifies that he / she is John Gerstner	JUN 0 2 2011 KCC WICHITA for
Abandonment procedure of pit: Let dry & backfilled pit. The undersigned hereby certifies that he / she is John Gerstner	JUN 0 2 2011 KCC WICHITA for
Abandonment procedure of pit: Let dry & backfilled pit. The undersigned hereby certifies that he / she is John Gerstner	JUN 0 2 2011 KCC WICHITA for Murfin Drilling Co, Inc (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Let dry & backfilled pit. The undersigned hereby certifies that he / she is John Gerstner a duly authorized agent, that all information shown hereon is true and correct to the John Gerstner	JUN 0 2 2011 KCC WICHITA for Murfin Drilling Co, Inc (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Let dry & backfilled pit. The undersigned hereby certifies that he / she is John Gerstner a duly authorized agent, that all information shown hereon is true and correct to the Location.	JUN 0 2 2011 KCC WICHITA forMurfin Drilling Co, Inc. (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent May