

GEORGE DOCKING
MARION BEATTY
HARRY G. WILES
RICHARD C. BYRD
RAYMOND B. HARVEY
CLYDE E. MILLIGAN

Governor Chairman Commissioner Commissioner Secretary Counsel

## State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water)
500 Insurance Bldg. 212 N. Market
WICHITA, KANSAS
JEWEL M. OGDEN, Director

C2 12-7-60

Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2, Kansas

Dear Sir:

have this date November 30, 1960, authorized the following
olugging operation:
perator's Full Name: Don McKellar
Complete Address: 812 Hancock, Salina, Kansas
ease Name: Jackman Well No. 3
Location: CW/2 NE NE Sec. 10 Twp. 15 Rge. 1 (E) (W)X
County: Saline Total Depth: 2560'
Oil Well Gas Well Input Well SWD Well D & A X
other well as hereafter indicated:
Operator was instructed to plug well as follows:
Gun pits and circulate heavy mud. Fill hole to 115' with heavy mud.
Gun pits and circulate heavy mud. Fill hole to 115' with heavy mud. Push plug and $\frac{1}{4}$ sack hulls to 115' and cement with 20 sacks thru
Push plug and 1/2 sack hulls to 115° and cement with 20 sacks thru
Push plug and \$\frac{1}{4}\$ sack hulls to 115' and cement with 20 sacks thru drill pipe. Fill hole to 40' with heavy mud. Push plug and \$\frac{1}{4}\$ sack
Push plug and \$\frac{1}{4}\$ sack hulls to 115' and cement with 20 sacks thru drill pipe. Fill hole to 40' with heavy mud. Push plug and \$\frac{1}{2}\$ sack hulls to 40' and cement with 10 sacks. Fill, bridge, and cement
Push plug and \$\frac{1}{4}\$ sack hulls to 115' and cement with 20 sacks thru drill pipe. Fill hole to 40' with heavy mud. Push plug and \$\frac{1}{2}\$ sack hulls to 40' and cement with 10 sacks. Fill, bridge, and cement

Very truly yours,

Signed: Conservation Division Agent