

Notice: Fill out COMPLETELY
and return to Conservation Division at
the address below within
60 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

OPERATOR: License #: 34318
Name: Berexco, L.L.C.
Address 1: P. O. Box 723
Address 2: 2020 N Bramblewood, Wichita KS 67201
City: Hays State: KS Zip: 67601 +
Contact Person: Curtis Gabel
Phone: (785) 628-6101
Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic
 Water Supply Well Other: _____ SWD Permit #: _____
 ENHR Permit #: _____ Gas Storage Permit #: _____
Is ACO-1 filed? Yes No If not, is well log attached? Yes No
Producing Formation(s): List All (if needed attach another sheet)
Topeka Depth to Top: 3100' Bottom: 3008 T.D. _____
Topeka Depth to Top: 3022 Bottom: 3028 T.D. _____
Topeka Depth to Top: 3036 Bottom: 3042 T.D. _____
Plugs 3136-60
A 2254-58 B 3248-74 E 3307-09 I 3396-3400

API No. 15 - .051.04953.00.00
Spot Description: _____
NE SW NE Sec. 22 Twp. 11 S. R. 18 East West
1,650 3726 Feet from North South Line of Section
1,650 1534 Feet from East West Line of Section
Footages Calculated from Nearest Outside Section Corner:
 NE NW SE SW
County: Ellis
Lease Name: Henderson Well #: A-2
Date Well Completed: 11-47
The plugging proposal was approved on: 11-18-11 (Date)
by: Rich Williams (KCC District Agent's Name)
Plugging Commenced: 11-21-11
Plugging Completed: 11-21-11

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface, Conductor & Production)			
Formation	Content	Casing	Size	Setting Depth	Pulled Out
		Surface	8 5/8	262'	0
		Production	5 1/2	3555'	0

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Perforate 2 holes at 750'-1300'-1850'. Run tubing to 3100', pump 100 sks cement, 60/40 pos w 4% gel with 300# hulls. Pull up to 2,100', mix 100 sks cement w 100# hulls, pull up to 1,100'. Mix 155 sks cement circulate to surface. Pull rest of tubing. Hook up to 8 5/8, pump 40 sks, press to 150#. Hook up to 5 1/2 pump 75 sks, press to 300# shut in and shut down. Witnessed by Bruce Rode KCC representative.

Plugging Contractor License #: 34318 Name: Berexco, L.L.C.
Address 1: P. O. Box 723 Address 2: 2020 N Bramblewood, Wichita KS 67201
City: Hays State: KS Zip: 67601 +
Phone: (785) 628-6101
Name of Party Responsible for Plugging Fees: Berexco, L.L.C.
State of Kansas County, Sedgwick, ss.
Curtis Gabel Employee of Operator or Operator on above-described well.
(Print Name)

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

Signature: Curtis Gabel

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

RECEIVED

NOV 28 2011

KCC WICHITA

AR