| 15-071-20313-00-00 STATE OF KANSAS STATE CORPORATION COMMISSION 200 Colorado Derby Bldg. Wichita, Kansas 67202

Form CP-4 Rev. 12-15-80

## WELL PLUGGING RECORD

Aske Required Affidavit  CXMINY Greeley SEC. 1 THP 165 RGE. 43 RAW Location as in quarters or footage from lines:  900 PM, 1650 PML  Lease Onner Lease Nome Gasall Well No. F #2  Office Address 1800 Lincoln Center Bldg., Denver, Colorado 80264 Character of Well (Completed as Oil, (as or Dry Hole): Dry Date Well Completed 1/21/84 Application for plugging filed 1/21/84 Plugging completed 1/21/84 Plugging completed 1/21/84 Plugging completed 1/21/84 Plugging completed 1/21/84 Reason for abandomment of well or producing formation No. reservoir sand Was permission obtained from the Conservation Division or it's Agent's before plugging was commenced? yes Name of Conservation Agent who supervised plugging of this well N/A Producing formation None Depth to top bottom T.D. 5500'  Show depth and thickness of all water, oil and gas formations.  Office Address Prom To Size Put in Nilled Our Formation: Content From To Size Put in Nilled Our Formation: Content Prom To Size Put in Nilled Our Formation Content Plugs were used, state the character of some and depth placed, from Feet or feet for each plug set, Set 40 sx cut plug from 1400' to 1250. Set 40 sx cut plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls s all cut plugs spotted through drill pipe s hole was filled w/ drilling mud.  SINTE OF CXMIY OF (employee of Conner) or (owner or operator) of the above-described well, being first duly swom on outh, says: That I have knowledge of the formation contained and the log of the above-described well as filled and that the same are true and correct. So help no God.  (Signature) Sufference of the above-described well as filled and that the same are true and correct. So help no God.  (Signature) Sufference of the bove-described well as filled and that the same are true and correct. So help no God.  (Signature) Sufference of the sufference of the above-described well as filled and that the same are true and correct. So help no God.  (Signature) Sufference of the sufference of the sufference of the above-des	Give All Info	ormation Compl	etely					
Lease Owner	Make Required	d Affidavit	COUNTY Gre	eley in quart	ers or	SEC. 1 footage fi	TWP. <u>16S</u> com lines:	RGE. <u>43</u> XEX/W
Lease Name Edsall well No. F #2  Office Address 1800 Lincoln Center Eldg. Denver. Colorado 80264  Character of Well (Completed as Oil, Gas or Dry Hole): Dry Date Well Completed 1/21/84  Application for plugging filled 1/21/84  Plugging commenced 1/21/84  Plugging completed 1/21/84  Plugging completed 1/21/84  Reason for abandonment of well or producing formation  No reservoir sand  Was permission obtained from the Conservation Division or it's Agent's before plugging was commenced? yes  Name of Conservation Agent who supervised plugging of this well N/A.  Producing formation None Depth to top bottom T.D. 5500'  Show depth and thickness of all water, oil and gas formations.  Casing Record  Formation Content From To Size Put in Pulled Out  Describe in detail the manner in which the well was plugged, indicating where the mad fluid was placed and the method or methods used in introducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet for each plug size. Set 40 8x ont plug from 1400' to 1250. Set 40 8x ont plug from 1500' to 150'. Set wooden bridge plug w/ 1/2 sx option seed hulls s 10 sxs of cmt from 40' to surface, 5 sxs in 88 5 sxs, in Mil.  All cmt plugs spotted through drill pipe s hole was filled w/ drilling mud.  State of County Of (employee of owner) or (owner or operator) of the above-described well, being first duly swom on oath, says: That I have knowledge of the facts, statements, and matters barein contained and the log of the above-described well as filled and that the same are true and correct. So help as Cod.  State Of (signature) Supervised Public.  State Onto Shorn to before me this 31 day of Supervised Public.			990' FWL,	1650' F	<u>NL</u>			
Office Address 1800 Lincoln Center Bidg., Denwer, Colorado 80264 Character of Well (Completed as Oil, Gas or Dry Hole): Dry Date Well Completed 1/21/84 Application for plugging filed 1/21/84 Plugging commenced 1/21/84 Plugging completed 1/21/84 Plugging was commenced? yes Name of Conservation Agent who supervised plugging was commenced? yes Name of Conservation Agent who supervised plugging was commenced? yes Now depth and thickness of all water, oil and gas formations.  OIL, GAS OR WATER RECORDS  Casing Record  Content From To Size Put in Fulled Out Power and state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used, state the character of same and depth placed, from feet or other plugs were used to save described well as feet of the same plug from 1400 to 1250. Set 40 sx or other plugs were used to save described well as filed and that the same are true and correct. So help me God.  (Signature)  STATE OF  COUNTY OF  (Signature)  STATE OF  COUNTY OF  (Signature)  STATE OF  COUNTY OF  (Signature)  (Address)			Lease Owner				Woll N	n # #2
Character of Well (Completed as Oil, Gas or Dry Hole): Dry  Date Well Completed 1/21/84  Application for plugging filed 1/21/84  Plugging commenced 1/21/84  Plugging completed 1/21/84  Reason for abandorment of well or producing formation  No reservoir sand  Mas permission obtained from the Conservation Division or it's  Agent's before plugging was commenced? Yes  Name of Conservation Agent who supervised plugging of this well N/A  Producing formation None Depth to top Dottom T.D. 5500'  Show depth and thickness of all water, oil and gas formations.  OIL, GAS OR WATER RECORDS  Casing Record  Formation Content From To Size Put in Pulled Our  Describe in detail the marner in which the well was plugged, indicating where the mid- fluid was placed and the method or methods used in introducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx cant plug from 1400' to 1550. Set 40 sx			Lease Name	Edsall			— WEIL IN	5. <u>F #2</u>
Date Well Completed 1/21/84  Application for plugging filed 1/21/84  Plugging commenced 1/21/84  Plugging commenced 1/21/84  Plugging completed 1/21/84  Plugging completed 1/21/84  Reason for abandorment of well or producing formation  No reservoir sand  Was permission obtained from the Conservation Division or it's Agent's before plugging was commenced? yes  Name of Conservation Agent who supervised plugging of this well N/A  Producing formation None Depth to top bottom T.D. 5500!  Show depth and thickness of all water, oil and gas formations.  OIL, CAS OR WATER RECORDS  Casing Record  Formation Content From 70 Size Put in Pulled Out  O 440 8-5/8" 440! None  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx cmt plug from 1400' to 1250. Set 40 sx  cmt plug from 500' to 350'. Set wooden bridge plug will 7/2 sx conton seed hulls s  10 sxs of cmt from 40' to surface, 5 sxs in RH is 5 sxs in MH.  All cmt plugs spotted through drill pipe s hole was filled w/ drilling mud.  State OF COUNTY OF Sxs in RH is 5 sxs in MH.  County OF Sxs or (conner or operator) of the above-described well, being first duly swom on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filed and that the same are true and correct. So help me God.  (Signature) Supervised well as filed and that the same are true and correct. So help me God.  (Signature) Supervised well as filed and that the same are true and correct. So help me God.  (Signature) Supervised well as filed and that the same are true and correct. So help me God.  (Signature) Supervised well as filed and that the same are true and correct. So help me God.  (Signature) Supervised well as filed and that the same are true and correct. So help me God.	ß							
Application for plugging filed    1/21/84			!					
Plugging commenced 1/21/84 Plugging completed 1/21/84 Reason for abandorment of well or producing formation  No reservoir sand			1	-				
Plugging completed   1/21/84			1					
Reason for abandomment of well or producing formation  No reservoir sand Was permission obtained from the Conservation Division or it's Agent's before plugging was commenced?  Yes  Name of Conservation Agent who supervised plugging of this well N/A  Producing formation None Depth to top bottom T.D. 5500'  Show depth and thickness of all water, oil and gas formations.  OIL, CAS OR WATER RECORDS  Casing Record  Formation Content From To Size Put in Pulled Out  O 440 8-5/8" 440' None  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hold. If cement for other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx cmt plug from 1400' to 1250. Set 40 sx cmt plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls s  10 sxs of cmt from 40' to surface, 5 sxs in RH & 5 sxs in RH.  All cmt plugs spotted through drill pipe s hole was filled w/ drilling mud.  (If additional description is necessary, use BACK of this sheet)  Name of Plugging Contractor Dowell  STATE OF			1 (20	-				<u> </u>
Name of Conservation Agent who supervised plugging was commenced?  Agent's before plugging was commenced?  Yes  Name of Conservation Agent who supervised plugging of this well  Producing formation  None  Depth to top  bottom  T.D. 5500'  Show depth and thickness of all water, oil and gas formations.  OIL, GAS OR WATER RECORDS  Casing Record  Formation  Content  From To Size Put in Pulled Out  Formation  Content  From To Size Put in Pulled Out  None  Describe in detail the manner in which the well was plugged, indicating where the mud  fluid was placed and the method or methods used in introducing it into the hold. If cement  or other plugs were used, state the character of same and depth placed, from  feet for each plug set. Set 40 sx cmt plug from 1400' to 1250. Set 40 sx  cmt plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls &  10 sxs of cmt from 40' to surface, 5 sxs in RH & 5 sxs in MH.  All cmt plugs spotted through drill pipe s hole was filled w/ drilling mad.  (If additional description is necessary, use BACK of this sheet)  Name of Plugging Contractor Dowell  STATE OF  COUNTY OF  (employee of owner) or (owner or operator) of the  above-described well, being first duly sworn on eath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filed and that the same are true and correct. So help me God.  (Signature)  Water Public.							oducing format	ion
Name of Conservation Agent who supervised plugging was commenced?  Agent's before plugging was commenced?  Pes  Name of Conservation Agent who supervised plugging of this well  N/A  Producing formation  None  Depth to top  bottom  T.D. 5500'  Show depth and thickness of all water, oil and gas formations.  OIL, CAS OR WATER RECORDS  Casing Record  Formation  Content  From To Size  Put in Pulled Out  None  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet or feet for each plug set. Set 40 sx cmt plug from 1400' to 1250. Set 40 sx cmt plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls & 10 sxs of cmt from 40' to surface, 5 sxs in RH & 5 sxs in RH.  All cmt plugs sported through drill pipe & hole was filled w/ drilling mud.  (If additional description is necessary, use BACK of this sheet)  Name of Plugging Contractor Dowell  STATE OF			No rese	rvoir san	ıd			
Agent's before plugging was commenced?    Yes   Name of Conservation Agent who supervised plugging of this well   N/A			Was permiss	sion obta	ined fr	om the Con	servation Divi	sion or it's
Producing formation None Depth to top bottom T.D. 5500'  Show depth and thickness of all water, oil and gas formations.  OIL, GAS OR WATER RECORDS  Casing Record  Formation  Content From To Size Put in Pulled Out  O 440 8-5/8" 440' None  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx out plug from 1400' to 1250. Set 40 sx out plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls & 10 sxs of cnt from 40' to surface, 5 sxs in BH & 5 sxs in MH.  All cnt plugs spotted through drill pipe & hole was filled w/ drilling mud.  (If additional description is necessary, use BACK of this sheet)  Name of Plugging Contractor Dowell.  STATE OF								
Producing formation None Depth to top bottom T.D. 5500'  Show depth and thickness of all water, oil and gas formations.  OIL, GAS OR WATER RECORDS  Casing Record  Formation  Content From To Size Put in Pulled Out  O 440 8-5/8" 440' None  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx out plug from 1400' to 1250. Set 40 sx out plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls & 10 sxs of cnt from 40' to surface, 5 sxs in BH & 5 sxs in MH.  All cnt plugs spotted through drill pipe & hole was filled w/ drilling mud.  (If additional description is necessary, use BACK of this sheet)  Name of Plugging Contractor Dowell.  STATE OF	Name of Cons	servation Agen	t who superv	ised plug	ging of	this well	N/A	
Show depth and thickness of all water, oil and gas formations.  OIL, GAS OR WATER RECORDS  Casing Record  Formation  Content From To Size Put in Fulled Out  0 440 8-5/8" 440' None  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet for each plug set. Set 40 sx cmt plug from 100' to 1250. Set 40 sx cmt plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls & 10 sxs of cmt from 40' to surface, 5 sxs in RH & 5 sxs in MH.  All cmt plugs spotted through drill pipe & hole was filled w/ drilling mud.  (If additional description is necessary, use BACK of this sheet)  Name of Plugging Contractor Dowell  STATE OF	Producing fo	ormation No	ne1	Depth to	top	bott	.cmT.I	). <u>5500'</u>
Casing Record  Formation  Content From To Size Put in Pulled Out  0 440 8-5/8" 440' None  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx cmt plug from 1400' to 1250. Set 40 sx cmt plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls &  10 sxs of cmt from 40' to surface, 5 sxs in RH & 5 sxs in MH.  All cmt plugs spotted through drill pipe & hole was filled w/ drilling mud.  STATE OF	Show depth a	and thickness	of all water	, oil and	gas fo	rmations.		
Formation  Content From To Size Put in Pulled Out  0 440 8-5/8" 440' None  Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx cmt plug from 1400' to 1250. Set 40 sx cmt plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls & 10 sxs of cmt from 40' to surface, 5 sxs in RH & 5 sxs in MH.  All cmt plugs spotted through drill pipe & hole was filled w/ drilling mud.  STATE OF								Casing Record
Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hold. If cement or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx cmt plug from 1400' to 1250. Set 40 sx cmt plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls & 10 sxs of cmt from 40' to surface, 5 sxs in RH & 5 sxs in MH.  All cmt plugs spotted through drill pipe & hole was filled w/ drilling mud.  STATE OF COUNTY OF (employee of owner) or (owner or operator) of the above-described well, being first duly sworn on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filed and that the same are true and correct. So help me God.  (Signature) Judy Norman God Address)  SUESCRIBED AND SMORN TO before me this 31 day of July 19 84  Wy Commission Empires Des. 14 1678  Notary Public.				From	To	Size	Put in	
fluid was placed and the method or methods used in introducing It into the body. Teacher or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx cmt plug from 1400' to 1250. Set 40 sx cmt plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls & 10 sxs of cmt from 40' to surface, 5 sxs in RH & 5 sxs in MH.  All cmt plugs spotted through drill pipe & hole was filled w/ drilling mud.  (If additional description is necessary, use BACK of this sheet)  Name of Plugging Contractor Dowell  STATE OF	Formation	<del></del>	Oncerc					None
fluid was placed and the method or methods used in introducing It into the body. Teacher or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx cmt plug from 1400' to 1250. Set 40 sx cmt plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls & 10 sxs of cmt from 40' to surface, 5 sxs in RH & 5 sxs in MH.  All cmt plugs spotted through drill pipe & hole was filled w/ drilling mud.  (If additional description is necessary, use BACK of this sheet)  Name of Plugging Contractor Dowell  STATE OF						1	<u> </u>	
fluid was placed and the method or methods used in introducing It into the body. Teacher or other plugs were used, state the character of same and depth placed, from feet to feet for each plug set. Set 40 sx cmt plug from 1400' to 1250. Set 40 sx cmt plug from 500' to 350'. Set wooden bridge plug w/ 1/2 sx cotton seed hulls & 10 sxs of cmt from 40' to surface, 5 sxs in RH & 5 sxs in MH.  All cmt plugs spotted through drill pipe & hole was filled w/ drilling mud.  (If additional description is necessary, use BACK of this sheet)  Name of Plugging Contractor Dowell  STATE OF		<del></del>		<u> </u>				
(If additional description is necessary, use BACK of this sheet)  Name of Plugging Contractor	cmt plug 10 sxs o	feet for each from 500' to f cmt from 40	on plug set.  350'. Set  to surface	wooden b	ridge p in RH &	olug W/ 1/ 5 sxs in	2 sx cotton se	eed hulls &
Name of Plugging Contractor	ALL GIIL	prugs spotted						
Name of Plugging Contractor								
Name of Plugging Contractor								
Name of Plugging Contractor				<del></del>	<del></del>			
Name of Plugging Contractor						PACY C	f this sheet)	<u></u>
above-described well, being first duly sworn on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filed and that the same are true and correct. So help me God.  (Signature)  (Address)	Name of Plu	(If additiona ugging Contrac	tor <u>Dowell</u>	1 is nece	ssary,	use DACK C	- Chira Sheecy	
above-described well, being first duly sworn on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filed and that the same are true and correct. So help me God.  (Signature)  (Address)								
above-described well, being first duly sworn on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filed and that the same are true and correct. So help me God.  (Signature)  (Address)	STATE OF		COUNTY OF			,ss.	,	
SUBSCRIBED AND SWORN TO before me this 31 day of July, 1984  Notary Public.	facts stat	ribed well, be	eing first du	ly sworn n contain	on oath ed and So he	i, says: I the log of lp me God.	That I have kno the above-de:	owledge of the scribed well a
SUBSCRIBED AND SWORN TO before me this 31 day of July, 1984  My Commission Expires Dec. 14 1873  Notary Public.					(Sig	mature)(	Track Wen	
My Commission Expires Dec. 14 1993 Notary Public.					2		// '0	
My Commission Expires Dec. 14 1873 Notary Public.	SUB:		WORN TO befor	e me this		-		anson
	My Commiss		My Commission a	apires Dec. 1	43. 1888		No	tary Public.

RECEIVED STATE CORPORATION COMMISSION

AUG 02 1984 OS-02-1984 CONSERVATION DIVISION Wichita, Kansas