## KANSAS STATE CORPORATION COMMISSION

WELL PLUGGING SUPERVISOR'S REPORT

TO:
Jewel M. Ogden, Director
500 Insurance Building
212 North Market

PUDS-23-58

Ke Osia
Location: NW-NW-SW
<b>5ec.</b> 20 Twp. 14 Rge. 2 (E) (W)
Total Depth: 3249
supervision of plugging of:
_LeaseVan Ness
st Supply Co. Inc.
06, Chase, Kansas
erator
License No. 14
as Well Input Well SWD Well D & A
ed dry hole did operators wait for you to arrive
Reason:
3: PM Day 16 Month May Year 1958
as follows:
cemented w/5 sacks. Mud to 180rock bridge
w/15 sacks. Mud to 20'bridge cemented to
5 sacks.
and the second s
above well was plugged as herein stated and that I was
ll was being plugged.
Signed Well Plugging Supervisor
$\mathcal{O}$
not present while the above well was being plugged, however e and belief it was plugged as herein stated. A full account as follows:
s as TOTTOWS:
ı
A Signad.
Signed:  Well Plugging Supervisor
FLUGGING
FILE SEC 20 T 14 R 2W BOOK PAGE 99 LINE 5