

KCC OIL/GAS REGULATORY OFFICES

Date: 01/13/12

District: 1

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

RECEIVED

JAN 25 2012

Operator License No: 31652

API Well Number: 15-083-21722-00-00

KCC WICHITA

Op Name: Norstar Petroleum, Inc.

Spot: SW-SE-NW-NE Sec 4 Twp 22 S Rng 23 E / W

Address 1: 88 Inverness Cir. E. Unit F104

1046 Feet from N / S Line of Section

Address 2: _____

1777 Feet from E / W Line of Section

City: Englewood

GPS: Lat: 38.17216 Long: 99.84995 Date: 1/13/12

State: CO Zip Code: 80112

Lease Name: Phillips-Denny Well #: 1-4

Operator Phone #: (303) 925-0696

County: Hodgeman

Reason for Investigation:

Company requested a state witness to the alternate II cementing job.

Problem:

Alternate II cementing requirements have not been met.

Persons Contacted:

None.

Findings:

8 5/8" was set @ 257'. 4 1/2" was set @ 4699' with 100 sx cement on primary cementing job. Company opened port collar @ 1580'. Swift Services, Inc. pumped 80 bbl of mud to condition the hole. Swift Services, Inc. then pumped 260 sx SMD cement, circulating 20 sx to the pit. Closed port collar.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

None. Alternate II cementing requirements have been met.
GPS converted footages are 1039' FNL & 1780' FEL.

Verification Sources:

Photos Taken: 0

- RBDMS
- T-I Database
- Other: On-site witness.
- KGS
- District Files
- TA Program
- Courthouse

By: Eric McLaren
Eric McLaren

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

RECEIVED
JAN 20 2012
KCC DODGE CITY

Form: _____