

STATE OF KANSAS
STATE CORPORATION COMMISSION
200 Colorado Derby Building
Wichita, Kansas 67202

WELL PLUGGING RECORD
K.A.R.-82-3-117

API NUMBER 15-169-20,231-00-01

LEASE NAME Muir

WELL NUMBER #1

SPOT LOCATION 660' FSL & 1320'
FEL C S/2 SE/4
SEC. 13 TWP. 15 SRGE. 3W (E) or (W)

LEASE OPERATOR Cal Jones

ADDRESS Canton, Kansas 67428

PHONE # (316) 628-4929 OPERATORS LICENSE NO. 5276

Character of Well D & A
(Oil, Gas, D&A, SWD, Input, Water Supply Well)

Did you notify the KCC/KDHE Joint District Office prior to plugging this well? Yes

Which KCC/KDHE Joint Office did you notify? Salina

Is ACO-1 filed? If not, is well log attached? Yes

Producing formation _____ Depth to top _____ bottom _____ T.D. _____

Show depth and thickness of all water, oil and gas formations.

OIL, GAS OR WATER RECORDS

CASING RECORD

Formation	Content	From	To	Size	Put in	Pulled out

Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used state, the character of same and depth placed, from feet to feet each set.

Bottom plug at 350' with 50 sacks of cement. Top plug at 60' with 25 sacks of cement. 10 sacks of cement in rathole. State Plugger, Gib Toman Holyrood, Kansas July 30, 1984

(If additional description is necessary, use BACK of this form.)


Name of Plugging-Contractor Blackstone Drilling, Inc. License No. 5927
Address P.O. Box 1184, McPherson, Kansas

STATE OF Kansas COUNTY OF McPherson, ss.

Cal Jones (employee of operator) or
(operator) of above-described well, being first duly sworn on oath, says: That
I have knowledge of the facts, statements, and matters herein contained and
the log of the above-described well as filed that the same are true and
correct, so help me God.

(Signature)

Canton, Kansas 67428


Shirley Warner
Notary Public

RECEIVED
STATE CORPORATION COMMISSION

AUG 08 1984

SUBSCRIBED AND SWEORN TO before me this 7 day of July, 1984

CONSERVATION DIVISION
Wichita, Kansas
My Commission expires:

May 26, 1987

I tried to wash the old hole down but only drilled to 740' and found a joint of surface pipe in the hole which was left from the original drilling of this well. It had not been on the copy of the other well plugging record I got from your office or I would not have tried to wash it down!

