15-169-19064-00-01

Form CP-3 Rev. 6-26-62

KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

J. P. Roberts
Assitant Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

MAY 3 1867

| Operator's Full Name Donald T. Ingling Complete Address: 615 First Nat'l Bank Bldg., Wichita, Kansas | | | | |
|---|--------------------------------|-------------|-------------|-------------------|
| | | | | |
| Location | SW SE SW | _Sec6 | Twp. 15 Rge | . 2 (E) (W) X |
| County | Saline | Tota | l Depth | 3505• |
| Abandoned Oil | WellGas WellInput | Well | _SWD Well_X | D & A |
| Other well as | hereafter indicated: | | | |
| Plugging Cont | ractor: Bert Self Casing Pulli | ng Co. | | |
| Address: R. R | . 🔑, Hutchinson, Kansas | | Licen | se No48 |
| Operation Completed: Hour 5 PM Day 27 Month April Year 1967 | | | | |
| The Above well was plugged as follows: | | | | |
| Hole filled with sand to 3450° and cemented with 3 sacks. | | | | |
| (Hole bridged over at 75°, and after spending 5 hours trying to knock bridge out, | | | | |
| decided to cement it at that point) Hole cemented to base of cellar with 6 yards | | | | |
| ready mix cement. (Apparently a good deal of this cement went on through the bridge, | | | | |
| as very little stayed in cellar. I actually think that the 145° of 20° casing is | | | | |
| full. as the hole was bridged off below the casing before plugging was started.) | | | | |
| | | | | |
| - | DATE 5/1/67 INV. NO. 5/36-W | | igned: | ugging Supervisor |