STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely Make Required Affidavit Mail or Deliver Report to:

WELL PLUGGING RECORD

State Corporation Commission P. O. Box 17027 Wichita, Kansas 67217	• • • • • • • • • • • • • • • • • • •	Ness County. Sec. 25 Twp. 16S Rge. (E) 25 (W)						
NORTH	Location as "NE/CNWXSWX" or footage from lines C/SW NE Lease Owner Patrick Petroleum Corporation Lesse Name Nelson Well No. 1							
	Office Address 330 Page Court, 220 West Douglas, Wichita, Kansas							
	Character of Well (completed as Oil, Gas or Dry Hole) Dry Hole Dry Hole							
	Date well completed December 20 19 73							
	Application for plugging filed Application for plugging approved				December 20 19 73 December 20 19 73 December 20 19 73			
.								
	Plugging commenced				December :	20	<u>19 73</u>	
	Plugging completed December 20 19 73 Reason for abandonment of well or producing formation Dry Hole							
	If a producing well is abandoned, date of last production							
-								
ì								
Locate well correctly on above Section Plat		Was permission obtained from the Conservation Division or its agents before plugging was commenced? Yes						
section Plat	menced?							
ducing formation	Time to gategorid positive	enth to ton	Bottom		Total Denth o	f Well 45	Feet	
w depth and thickness of all water,	oil and gas formation	s	Dottom		. Ivai Depart	/1 VV (/ 	<u></u>	
w deput and unexpess of all water,	, ou and gas roumadess	D.						
OIL, CAS OR WATER RECORD	OS					CASING R	ECORD	
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLE	D DUT	
	8-5/8"	0	284.761					
					· · · · · · · · · · · · · · · · · · ·			
					- 			
								
			- 					
		<u> </u>			 			
				······································				
feet for each plug se ugged hole as follows:	nent or other plugs weret. Plugged at	re used, state 1	the character of 70 sacks	f same and dep of 50-50	pozmix & 6	6% gel;)	feet to	
ntroducing it into the hole. If cen feet for each plug se ugged hole as follows: 240' with 20 sacks of	nent or other plugs weret. Plugged at	re used, state 1 745' with & 6% gel	the character of 70 sacks plugged	of 50-50 at 40' w	pozmix & 6	6% gel;)	feet to	
Introducing it into the hole. If cen- feet for each plug se tugged hole as follows: t 240' with 20 sacks of	nent or other plugs we et. : Plugged at 7 6 50-50 pozmix	re used, state 1 745' with & 6% gel	the character of 70 sacks plugged	of 50-50 at 40' w	pozmix & 6	6% gel;)	feet to	
ntroducing it into the hole. If cen feet for each plug se ugged hole as follows: 240' with 20 sacks of	nent or other plugs we et. : Plugged at 7 6 50-50 pozmix	re used, state 1 745' with & 6% gel	the character of 70 sacks plugged	f same and deport of 50-50 at 40' w: .973.	pozmix & (ith 10 sac)	6% gel;) ks of 50	olugged -50	
ntroducing it into the hole. If cen feet for each plug se ugged hole as follows: 240' with 20 sacks of	nent or other plugs we et. : Plugged at 7 6 50-50 pozmix	re used, state 1 745' with & 6% gel	the character of 70 sacks plugged	of 50-50 at 40' w	pozmix & (ith 10 sac)	6% gel;) ks of 50	olugged -50	
ntroducing it into the hole. If cen feet for each plug se ugged hole as follows: 240' with 20 sacks of	nent or other plugs we et. : Plugged at 7 6 50-50 pozmix	re used, state 1 745' with & 6% gel	the character of 70 sacks plugged	f same and deport of 50-50 at 40' w: .973.	pozmix & (ith 10 sac)	6% gel;)	olugged -50	
ntroducing it into the hole. If cen feet for each plug se ugged hole as follows: 240' with 20 sacks of	nent or other plugs we et. : Plugged at 7 6 50-50 pozmix	re used, state 1 745' with & 6% gel	the character of 70 sacks plugged	f same and deport 50-50 at 40' w: 973.	RECEIVE CORPURATION	6% gel;) ks of 50	olugged -50	
ntroducing it into the hole. If cen feet for each plug se ugged hole as follows: 240' with 20 sacks of	nent or other plugs we et. : Plugged at 7 6 50-50 pozmix	re used, state 1 745' with & 6% gel	the character of 70 sacks plugged	f same and deport 50-50 at 40' w: 973.	RECEIVE CORPURATION	6% gel;) ks of 50	olugged -50	
ntroducing it into the hole. If cen feet for each plug se ugged hole as follows: 240' with 20 sacks of	nent or other plugs we et. : Plugged at 7 6 50-50 pozmix	re used, state 1 745' with & 6% gel	the character of 70 sacks plugged	f same and deport of 50-50 at 40' with a state of same and deport of s	RECEIVE CORPURATION	G% gel;) Ks of 50 COMMISSION	olugged -50	
ntroducing it into the hole. If cen feet for each plug se tugged hole as follows: 240' with 20 sacks of	nent or other plugs we et. : Plugged at 7 6 50-50 pozmix	re used, state 1 745' with & 6% gel	the character of 70 sacks plugged	f same and deport of 50-50 at 40' with a state of same and deport of s	RECEIVE CORPURATION	G% gel;) Ks of 50 COMMISSION	olugged -50	
introducing it into the hole. If center feet for each plug se tugged hole as follows: t 240' with 20 sacks of	nent or other plugs we et. : Plugged at 7 6 50-50 pozmix	re used, state 1 745' with & 6% gel	the character of 70 sacks plugged	f same and deport of 50-50 at 40' with a state of same and deport of s	RECEIVE CORPURATION	G% gel;) Ks of 50 COMMISSION	olugged -50	
Introducing it into the hole. If cen- feet for each plug se tugged hole as follows: t 240' with 20 sacks of	nent or other plugs weret. : Plugged at 7 ? 50-50 pozmix down at 7:30 P.	re used, state (745' with & 6% gel. M. Decer	the character of 70 sacks plugged aber 20, 1	f same and deport 50-50 at 40' with 973.	RECEIVE CORPURATION	G% gel;) Ks of 50 COMMISSION	olugged -50	
ntroducing it into the hole. If cem feet for each plug se Lugged hole as follows: 240' with 20 sacks of pamix & 6% gel. Plug of	nent or other plugs werest. : Plugged at 7 ? 50-50 pozmix down at 7:30 P.	re used, state to 745' with & 6% gel. M. Decer	casery, use BACK	f same and deport 50-50 at 40' with 973.	RECEIVE CORPURATION	G% gel;) Ks of 50 COMMISSION	olugged -50	
ntroducing it into the hole. If cem feet for each plug se ugged hole as follows: 240' with 20 sacks of exmix & 6% gel. Plug of	nent or other plugs weret. : Plugged at 7 ? 50-50 pozmix down at 7:30 P.	description is need a Drilling	cssery, use BACK	f same and deport of 50-50 at 40' w: 973. STATE CONS	RECEIV CORPURATION D CERVATION D Vicinita, Kans	G% gel;) Ks of 50 COMMISSION	olugged -50	
Introducing it into the hole. If cem feet for each plug se Lugged hole as follows: t 240' with 20 sacks of ozmix & 6% gel. Plug of	nent or other plugs weret. : Plugged at 7 ? 50-50 pozmix down at 7:30 P.	description is need a Drilling	casery, use BACK	f same and deport of 50-50 at 40' w: 973. STATE CONS	RECEIV CORPURATION D CERVATION D Vicinita, Kans	G% gel;) Ks of 50 COMMISSION	olugged -50	
introducing it into the hole. If cer feet for each plug se lugged hole as follows: t 240' with 20 sacks of ozmix & 6% gel. Plug of me of Plugging Contractor dress ATE OF KANSAS Char Char	cent or other plugs were to the plugged at 7 center of pozmix down at 7:30 P. (If edditional Strate P. O	description is need a Drilling Box 355. NTY OF	casery, use BACK The Character of To sacks plugged wher 20, 1 casery, use BACK The Careat Ben BARTON (employee of of facts, stateme	same and deport 50-50 at 40' with 973. STATE CONS of this sheet) id, Kansas	RECEIVE CORPORATION DEC 28 10 SERVATION DAISHITA, Kans	Go gel;) ks of 50- COMMISSION 373 VIVISION 3s	olugged -50	
introducing it into the hole. If cem feet for each plug se lugged hole as follows: t 240' with 20 sacks of ozmix & 6% gel. Plug of mme of Plugging Contractor ddress	cent or other plugs were et. Plugged at 7	description is need a Drilling Box 355. NTY OF	casery, use BACK The Character of To sacks plugged wher 20, 1 casery, use BACK The Careat Ben BARTON (employee of of facts, stateme	same and deport 50-50 at 40' with 973. STATE CONS of this sheet) id, Kansas	RECEIVE CORPORATION DEC 28 10 SERVATION DAISHITA, Kans	Go gel;) ks of 50- COMMISSION 373 VIVISION 3s	olugged -50	
introducing it into the hole. If cem feet for each plug se lugged hole as follows: t 240' with 20 sacks of ozmix & 6% gel. Plug of me of Plugging Contractor dress ATE OF KANSAS Char II, being first duly sworn on oath, s	cent or other plugs were et. Plugged at 7	description is need a Drilling Box 355. NTY OF	essery, use BACK 3, Inc. Great Ben BARTON (employee of or facts, stateme help ms God.	same and deport 50-50 at 40' w. 973. STATE CONS of this sheet) ad, Kansas where or (54)	RECEIVE CORPORATION DEC 28 10 ERVATION DAISTINA Mans 67530 38. Steines Steines	ED COMMISSION 373	re-described log of the	
introducing it into the hole. If cem feet for each plug se lugged hole as follows: t 240' with 20 sacks of ozmix & 6% gel. Plug of me of Plugging Contractor dress ATE OF KANSAS Char II, being first duly sworn on oath, s	cent or other plugs were et. Plugged at 7	description is need a Drilling Box 355. NTY OF	essery, use BACK 3, Inc. Great Ben BARTON (employee of or facts, stateme help ms God.	same and deport 50-50 at 40' w. 973. STATE CONS of this sheet) ad, Kansas where or (54)	RECEIVE CORPORATION DEC 28 10 SERVATION DAISTINATION DAIS	ED COMMISSION 373	re-described log of the	
me of Plugging Contractor dress ATE OF KANSAS Char Kansas Kansas	enent or other plugs were et. Plugged at 7	description is need a Drilling Box 355, NTY OF amp whedge of the decreet. So	casery, we BACK g, Inc. Great Ben BARTON (employes of of facts, statemes help me God. Ch.	same and deport 50-50 at 40' w. 973. STATE CONS of this sheet) id, Kansas wher) or (** arles W. O. Box	RECEIVE CORPORATION DEC 28 10 SERVATION DISCIPLIA, I (ans. Steincamp., 355. Great (Azidress)	ED COMMISSION 73 VISION 35 Preside Bend, Ka	re-described log of the	
me of Plugging Contractor dress ATE OF KANSAS Char Kansas Kansas	cent or other plugs were et. Plugged at 7	description is need a Drilling Box 355, NTY OF amp whedge of the decreet. So	casery, we BACK g, Inc. Great Ben BARTON (employes of of facts, statemes help me God. Ch.	same and deport 50-50 at 40' w. 973. STATE CONS of this sheet) ad, Kansas where or (54)	RECEIVE CORPORATION DEC 28 10 SERVATION DISCIPLIA, I (ans. Steincamp., 355. Great (Azidress)	ED COMMISSION 373	re-described log of the	
introducing it into the hole. If cer feet for each plug se lugged hole as follows: t 240' with 20 sacks of ozmix & 6% gel. Plug of ame of Plugging Contractor	enent or other plugs were et. Plugged at 7	description is need a Drilling Box 355, NTY OF amp whedge of the decreet. So	casery, we BACK g, Inc. Great Ben BARTON (employes of of facts, statemes help me God. Ch.	same and deport 50-50 at 40' w. 973. STATE CONS of this sheet) id, Kansas wher) or (** arles W. O. Box	RECEIVE CORPORATION DEC 28 10 SERVATION DISCIPLIA, I (ans. Steincamp., 355. Great (Azidress)	ED COMMISSION 73 VISION 35 Preside Bend, Ka	re-described log of the	

DRILLERS LOG

#1 Nelson

CASING RECORD:

279.76' of new 8-5/8"

surface casing.

COMPANY:

Patrick Petroleum Corporation

DECRIPTION: C/SW NE

Section 25-16S-25W

Ness County, Kansas

CONTRACTOR:

Strata Drilling, Inc.

TOTAL DEPTH:

45451

COMMENCED:

December 9, 1973

COMPLETED:

December 20, 1973

D. & A.

	,		
FORMATION	FROM	TO	REMARKS
Shale w/Sand Streaks Shale Shale w/Sand Streaks Shale & Sand Shale w/Lime Streaks Lime & Shale Lime Lime & Shale Lime Lime Lime Lime & Shale Lime	0 295 345 1175 1902 2560 3960 4050 4238 4340 4440	295 345 1175 1902 2560 3960 4050 4238 4340 4440 4545	Ran 279.76' of new 8-5/8" surface casing; set and cemented at 284.76' with 175 sacks of common cement, 2% gel and 3% C. C. Plug down at 1:30 A. M. December 10, 1973. STATE CORPORATION COMMISSION CONSERVA
ROTARY TOTAL DEPTH: 4545'			Ran electric lagration Division
•			-11252 -014

D. & A.

Plugged hole as follows: Plugged at 745' with 70 sacks of 50-50 pozmix & 6% gel; plugged at 240' with 20 sacks of 50-50 pozmix & 6% gel; plugged at 40' with 10 sacks of 50-50 pozmix & 6% gel. Plug down at 7:30 P. M. December 20, 1973.

STATE OF KANSAS)) ss. COUNTY OF BARTON)

I certify that this is a true and correct copy of the above log to the best of my knowledge.

STRATA DRILLING, INC.

W. Stemany W. Steincamp, President

.....Subscribed and sworn to before me this 21st day of December, 1973.