

KCC OIL/GAS REGULATORY OFFICE

DATE 2/17/95

[] New Situation
[x] Response to Request
[] Follow-up

OPERATOR Coyote, Inc. # 31565

NAME 217 S. Broadway
&
ADDRESS Wichita, KS 67202

LOCATION SE SW W/2 W/2, SEC 23, T 16 S, R 25 N W

LEASE Nuttle Well # 1-23

PHONE NO. 316-263-1200 OTHER _____

COUNTY Ness API# 15-135-23,845

REASON FOR INVESTIGATION: Alternate II cementing

PROBLEM: _____

PERSON(S) CONTACTED: _____

FINDINGS: Opened port collar at 1983'. Halliburton pumped in 375 sx lite cement.
Circulated 15 sx to pit. Started at 11:30 a.m. and completed at 12:15 p.m.

LEASE INSPECTION

COMPLAINT

STATE CORPORATION COMMISSION

FEB 22 1995

CONSERVATION DIVISION
WICHITA, KANSAS

ACTION/RECOMMENDATIONS: Alternate II cementing completed satisfactorily. photos taken: _____

FIELD REPORT

Retain 1 copy Joint District Office
Send 1 copy Conservation Division

By Steve Middleton
2/17/95