STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH EROADWAY
WICHITA, KANSAS

## WELL PLUGGING APPLICATION FORM File One Copy

Lease	Owner Welc	h & Olsson Drlg. Go	• Addres	s 203 Rule	Bldg. Wichit	a, Kansas.	
(A = = 1 4		Michaelis			Well No.	•	
		SW SE		Sec . 20	Twp. 16 Rge.25	_( <b>E</b> ) - (W)	
County	Ness			_Field Na	me (if any)	None	
		5' 0i1_					
		d with application?					
<del></del>	• · · · · · · · · · · · · · · · · · · ·		<del></del>	······································	······································		
Date a	nd hown plu	rating to desired to		2-2-56		<del></del>	
		gging is desired to					
Pluggi	ng of the w	ell will be done in	accorda	nce with t	the Rules and R	egulations	
of the	State Corp	oration Commission.					
Name o	f the perso	n on the lease in c	harge of	well for	cwner		
	Jack Parret		Addres	s Box 4	31. Great Bend	Kansas.	
Pluggi	ng Contract	or Welch & Olsson					
Pluggi	ng Contract	or's License No	None				
Addres	s 203 Rui	le Bldg. Wichita, K	ansas.				
Invoice	e covering	assessment for plug	ging thi	s well sho	ould be sent to	•	
Welch	& Olsson D	rlg. Co. Inc.	Addres	s 203 Rul	e Bldg. Wichit	a, Kansas	
and pay	yment will	be guaranteed by ap	pli <b>cant</b> 。		<b>\</b>	•	
			Welch	& Olssbu	) D≠11721mg Gompai	ny. Inc.	

2-6-56

Date

49236 F

William In About to

PLUGGING
PALE 5:32 1 16 R 25 N
DOCK MC 36 LINE 38

15-135-30409-00-00



STATE OF KANSAS

## STATE CORPORATION COMMISSION CONSERVATION DIVISION 211 NORTH BROADWAY WICHITA, KANSAS

February 6, 1956

Well No. Lease Description County File No. l Michaelis SW SW SE 20-16-25W Ness 36-38

Rooney-Siegfried & Thomas 203 Rule Building Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr.

STATE CORPORATION COMMISSION CONSERVATION DIVISION

S. S. Greider WELL PLUGGING SUPERVISOR

C: ictmint Dlanes

District Plugging Supervisor