

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

OPERATOR: License #: 31074
Name: Brake Oil
Address 1: 33527 2nd Road
Address 2: _____
City: Latham State: KS Zip: 67072 + _____
Contact Person: _____
Phone: (620) 965-2297
Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic
 Water Supply Well Other: _____ SWD Permit #: _____
 ENHR Permit #: _____ Gas Storage Permit #: _____
Is ACO-1 filed? Yes No If not, is well log attached? Yes No
Producing Formation(s): List All (if needed attach another sheet)
_____ Depth to Top: _____ Bottom: _____ T.D. _____
_____ Depth to Top: _____ Bottom: _____ T.D. _____
_____ Depth to Top: _____ Bottom: _____ T.D. _____

API No. 15 - 047-30071.00.00
Spot Description: _____
C NW NE Sec. 20 Twp. 23 S. R. 19 East West
532-4648 Feet from North / South Line of Section
1974 1958 Feet from East / West Line of Section
GPS-KCC
Footages Calculated from Nearest Outside Section Corner:
 NE NW SE SW
County: Edwards
Lease Name: Ploger Well #: 1
Date Well Completed: _____
The plugging proposal was approved on: _____ (Date)
by: Richard Lacey (KCC District Agent's Name)
Plugging Commenced: 1/16/12
Plugging Completed: 1/17/12

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface, Conductor & Production)			
Formation	Content	Casing	Size	Setting Depth	Pulled Out
			8-5/8"	283'	None
			5-1/2"	4600'	1600'

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Set plug @ 4145', dumped 3sx on top of plug. Got 14" stretch. Tried cutting @ 2000'. Cut pipe loose @ 1600'. Pulled casing out. Ran in with 1400' of 2-3/8. Copeland pumped 20gel 50sx @ 1400'. Pulled up to 560', pumped 50sx. Pulled up to 310', pumped 50sx. Pulled up to 40', cement circulated to surface. Plugging Complete.

RECEIVED

FEB 23 2012

Plugging Contractor License #: 31529 **KCC WICHITA** Name: Mike's Testing & Salvage, Inc.
Address 1: PO Box 467 Address 2: _____
City: Chase State: KS Zip: 67524 + _____
Phone: (620) 938-2943

Name of Party Responsible for Plugging Fees: Mike Kelso Oil
State of KS County, Rice, ss.
Mike Kelso Employee of Operator or Operator on above-described well.
(Print Name)

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

Signature: Mike Kelso