To: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202		APPROX. SW 15- 101-20.992 -60- 60	
		<del></del>	6 , t 16 s, R 28 W
		4050 feet XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
TECHNICIAN	N'S PLUGGING REPORT	2310	Teet XKRHXNXEXRREXXXXXXX
Operator l	icense # 5151	Lease Name Jame	s
Operator:	Gear Petroleum Co., Inc.	County	Lane
	300 Sutton Place Well Total Depth 4359 141,67		h 4359 141,67 te
	Wichita, KS 67202	Conductor Pipe:	Slzefeet
			\$1ze 8 5/8 feet 340
Abandoned	Oll Well Gas Well	Input Well	SWD WellD&A_X
	1 as hereinafter indicated		
	Contractor Warrior Drilling Com		
	905 Century Plaza, Wichita, K		
	o plug at: Hour: 3:00 pm Day:		
	proposal received from		
	name) Warrior		
	to fill hole with heavy mud a	nd spot cement throu	gh drill pipe PECLIVED
lst plu	ig at 1950' with 50 sx cement		STATE CORPORATION CO TAILS
2nd plu	ig at 900' with 50 sx cement		P3 · 00 · F0
3rd plu	ig at 360' with 40 sx cement solid bridge		(IIII 06 C)
/+h plu	solid bridge <sub>1g hulls - plug at 40' cement</sub>	to surface with 10	SX Cement
6th plu	ig to circulate rat hole with 10	sx cement, 7th plug	g to circulate mouse hole '
10_sx_c	coment.		(TECHNICIAN)
Plugging	Operations attended by Agent?:	AllPart	None X
	ns Completed: Hour: 5:30 pm Day		
Operation			
	HEGING REPORTIST Plug at 1950'	MICH DO BY COMCHE!	
ACTUAL PL	LUGGING REPORT 1st plug at 1950'		
cement,	, 3rd plug at 360' with 40 sx ce	ment, 4th & 5th plug	gs - solid bridge - hulls
cement,	, 3rd plug at 360' with 40 sx ce t 40' cement to surface with	ment, 4th & 5th plug	us - solid bridge - hulls
cement,	, 3rd plug at 360' with 40 sx ce	ment, 4th & 5th plug	us - solid bridge - hulls
cement,	, 3rd plug at 360' with 40 sx ce t 40' cement to surface with	ment, 4th & 5th plug	us - solid bridge - hulls
cement,	, 3rd plug at 360' with 40 sx ce t 40' cement to surface with	ment, 4th & 5th plug	us - solid bridge - hulls
cement, plug at	, 3rd plug at 360' with 40 sx ce t 40' cement to surface with cement, 7th plug to circulate mo	ment, 4th & 5th plug 10 sx cement, 6th plug ouse hole with 10 sx by Allied.	gs - solid bridge - hulls  lug to circulate rat hole  cement.
cement, plug at  10 sx c	Used 60/40 Pozmix 2% gel 3% cc	ment, 4th & 5th plug 10 sx cement, 6th plug use hole with 10 sx by Allied. Is necessary, use BA	gs - solid bridge - hulls  lug to circulate rat hole  cement.
cement, plug at  10 sx c	, 3rd plug at 360' with 40 sx ce t 40' cement to surface with cement, 7th plug to circulate mo	ment, 4th & 5th plug 10 sx cement, 6th plug use hole with 10 sx by Allied. Is necessary, use BA	gs - solid bridge - hulls  lug to circulate rat hole  cement.
cement, plug at  10 sx c	Used 60/40 Pozmix 2% gel 3% cc  (If additional description  (If additional description	by Allied.  Is necessary, use BA	Lug to circulate rat hole cement.  CK of this form.)
cement, plug at 10 sx c	Used 60/40 Pozmix 2% gel 3% cc	by Allied.  Is necessary, use BA	gs - solid bridge - hulls  lug to circulate rat hole  cement.