	KANSAS 67202 Nn's Plugging Report	330 feet from \$	
	· · ·	2310teet from E	
	Bankoff Oil Company	Lease Name Magie Well	/
Operator: Name& Address		CountyLane	145.
	6202 S. Lewis, Suite 176	Weil Total Depth 4480	f+
	P.O. Box 700657	Conductor Pipe: Size	feet
	Tulsa, OK 74170	Surface Casing: Size 8 5/8 fee	at
Abandoned	Oli Weil X Gas Well	Input WellSWD Well	D&A
	1 as hereinafter indicated		
Plugging	Contractor Kelso Casing	Pulling, Inc. License Number	6050
	P.O. Box 347, Chase, KS 67524		
Company t	o plug at: Hour: 3:30 p.m. Day:	30 Month: 3 Year	02
	proposal received from Mike Kels		: 19 <u>92</u>
	•		
(company	Relso Casing Pulling, Inc	(phone) ³¹	6-938-2943
were: 55"	at 4479' w/120 sx cement. Perfs	at 4295-4300'	<u>.</u>
1st plug	sand back to 4240° and dump 5 sx	cement on top of sand through bailer,	
2nd plug	pump 50 sx cement at 2190', 3rd	olug pump 80 sx cement at 1200',	
2nd plug		olug pump 80 sx cement at 1200',	
2nd plug	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p	olug pump 80 sx cement at 1200', lug pump 10 sx cement at 40'.	
2nd plug	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p	plug pump 80 sx cement at 1200', lug pump 10 sx cement at 40'. Richard Lace	у
2nd plug 4th plug	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p	olug pump 80 sx cement at 1200', lug pump 10 sx cement at 40'. Richard Lace (TECHNIC)	у
2nd plug 4th plug Plugging	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p Plugging Pro Operations attended by Agent?:	Doug pump 80 sx cement at 1200', Lug pump 10 sx cement at 40'. Richard Lace (TECHNICI X Part None	y AN)
2nd plug 4th plug Plugging Operation	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p Plugging Pro Operations attended by Agent?: S Completed: Hour: 7 p.m. Day:	Doug pump 80 sx cement at 1200', Lug pump 10 sx cement at 40'. Richard Lace (TECHNICI X Part None 30 Month: 3 Year	y AN) :19 92
2nd plug 4th plug Plugging Operation	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p Plugging Pro Operations attended by Agent?: S Completed: Hour: 7 p.m. Day:	Doug pump 80 sx cement at 1200', Lug pump 10 sx cement at 40'. Richard Lace (TECHNICI X Part None	y AN) :19 92
2nd plug 4th plug Plugging Operation ACTUAL PL	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p Plugging Pro Operations attended by Agent?: s Completed: Hour: 7 p.m. Day: ugging REPORT 1st plug sanded ba	Doug pump 80 sx cement at 1200', Lug pump 10 sx cement at 40'. Richard Lace (TECHNICI X Part None 30 Month: 3 Year	y AN) :19 92
2nd plug 4th plug Plugging Operation ACTUAL PL through b	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p Plugging Pro Operations attended by Agent?: s Completed: Hour: 7 p.m. Day: ugging REPORT 1st plug sanded ba	colug pump 80 sx cement at 1200', lug pump 10 sx cement at 40'. Richard Lace (TECHNICI X Part None 30 Month: 3 Year ek to 4240' and dumped 5 sx cement on	y AN) :19 92
2nd plug 4th plug Plugging Operation ACTUAL PL through b 2nd plug	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p Plugging Pro Operations attended by Agent?: s Completed: Hour: 7 p.m. Day: ugging REPORT 1st plug sanded ba	clug pump 80 sx cement at 1200', lug pump 10 sx cement at 40'. Richard Lace (TECHNIC) X Part None 30 Month: 3 Year k to 4240' and dumped 5 sx cement on	y AN) :19 92
2nd plug 4th plug Plugging Operation ACTUAL PL through b 2nd plug 3rd plug	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p Plugging Pro Operations attended by Agent?: s Completed: Hour: 7 p.m. Day: UGGING REPORT 1st plug sanded ba ailer, shot casing at 1200' and spotted shot casing loose at 800' and spo	clug pump 80 sx cement at 1200', lug pump 10 sx cement at 40'. Richard Lace (TECHNICI X Part None 30 Nonth: 3 Year k to 4240' and dumped 5 sx cement on 30 sx cement, 40 sx cement,	y AN) :19 92
2nd plug 4th plug Plugging Operation ACTUAL PL through b 2nd plug 3rd plug 4th plug	pump 50 sx cement at 2190', 3rd pump 50 sx cement at 360', 5th p Plugging Pro Operations attended by Agent7: s Completed: Hour: 7 p.m. Day: ugging REPORT 1st plug sanded ba ailer, shot casing at 1200' and spotted	Clug pump 80 sx cement at 1200', Lug pump 10 sx cement at 40'. Richard Lace (TECHNICI X Part None 30 Month: 3 Year 2k to 4240' and dumped 5 sx cement on 30 sx cement, 40 sx cement,	y AN) :19 92

FORM CP-2/3