	ION DIVISION - PLUGGING SECTION	C NW SW, SEC. 16, T 26 S, R 35 W
	ADO DERBY BUILDING Kansas 67202	1980feet from S section III
TECHNICIA	N'S PLUGGING REPORT	4620 feet from E section III
Operator	License # 5003	Lease Name White Well # 1-16
	McCoy Petroleum Corporation	County Kearny 172.3
Name& Address	110 South Main, Suite 500	Well Total Depth 5302 fee
•	Wichita, KS 67202	
		Surface Casing: Size 8 5/8 feet 1878
Abandoned	Oll Well Gas Well X	Input Well SWD Well D&A
•	1 as hereinafter indicated	SHD WELL DEA
	Contractor Hayes Well Service	5429
	.0. Box 108, Attica, KS 67009	License Number 5429
		29 / 89
	plug at: Hour: 10 a.m. Day:	
	proposal received from Dar	
(company r	McCoy Petroleum	(phone)(phone)
were: <u>5½"</u>	at 4610' PBTD 4452' Perfs at	4432-36' TOC 3500'
lst plug	set CIBP at 4400' and dump 2 sx	cement on top of sand through bailer,
•		
2nd plug	pump 100 sx cement at 2800', 3	rd plug pump 50 sx cement at 1900',
	pump 100 sx cement at 2800', 3: pump 40 sx cement at 1000',	rd plug pump 50 sx cement at 1900',
4th plug		rd plug pump 50 sx cement at 1900',
4th plug	pump 40 sx cement at 1000',	
4th plug	pump 40 sx cement at 1000',	posal Received by Richard W. Lacey (TECHNICIAN)
4th plug 5th plug	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro	posal Received by Richard W. Lacey
4th plug 5th plug Plugging 0	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?:	posal Received by Richard W. Lacey (TECHNICIAN) All Part None
4th plug 5th plug Plugging C	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?:	posal Received by Richard W. Lacey (TECHNICIAN) All Part None X 29 Month: 4 Year:19 89
4th plug 5th plug Plugging C Operations	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?: Completed: Hour:2:30 p.m. Day:	Posal Received by Richard W. Lacey (TECHNICIAN) All Part None
4th plug 5th plug Plugging Coperations ACTUAL PLU 2fid plug	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?: Completed: Hour:2:30 p.m. Day: GGING REPORT 1st plug set CIBP at 2817' with 100 sx cement,	Posal Received by Richard W. Lacey (TECHNICIAN) All Part None 29 Month: 4 Year:19 89 at 4400' with 2 sx cement,
4th plug 5th plug Plugging Coperations ACTUAL PLU 2fid plug 3rd plug	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?: Completed: Hour:2:30 p.m. Day:	Posal Received by Richard W. Lacey (TECHNICIAN) All Part None X 29 Month: 4 Year:19 89 at 4400' with 2 sx cement, RECEIVED STATE CORPORATION COMMISSION
4th plug 5th plug Plugging Coperations ACTUAL PLU 2nd plug 3rd plug 4th plug	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?: Completed: Hour:2:30 p.m. Day: GGING REPORT 1st plug set CIBP at 2817' with 100 sx cement, at 1947' with 50 sx cement, at 1006' with 40 sx cement,	Posal Received by Richard W. Lacey (TECHNICIAN) All Part None X 29 Month: 4 Year:19 89 at 4400' with 2 sx cement, RECEIVED STATE CORPORATION COMMISSION MAY 3 1989
4th plug 5th plug Plugging Coperations ACTUAL PLU 2nd plug 3rd plug 4th plug	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?: Completed: Hour:2:30 p.m. Day: GGING REPORT 1st plug set CIBP at 2817' with 100 sx cement, at 1947' with 50 sx cement,	Posal Received by Richard W. Lacey (TECHNICIAN) All Part None X 29 Month: 4 Year: 19 89 at 4400' with 2 sx cement, RECEIVED STATE CORPORATION COMMISSION MAY 3 1989 CONSERVATION DIVISION
4th plug 5th plug Plugging Coperations ACTUAL PLU 2nd plug 3rd plug 4th plug 5th plug	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?: Completed: Hour:2:30 p.m. Day: GGING REPORT 1st plug set CIBP at 2817' with 100 sx cement, at 1947' with 50 sx cement, at 1006' with 40 sx cement, at 62' with 13 sx cement.	Posal Received by Richard W. Lacey (TECHNICIAN) All Part None X 29 Month: 4 Year: 19 89 at 4400' with 2 sx cement, RECEIVED STATE CORPORATION COMMISSION MAY 3 1989 CONSERVATION DIVISION WICHIES: REMESS
4th plug 5th plug Plugging Coperations ACTUAL PLU 2nd plug 3rd plug 4th plug 5th plug	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?: Completed: Hour:2:30 p.m. Day: GGING REPORT 1st plug set CIBP at 2817' with 100 sx cement, at 1947' with 50 sx cement, at 1006' with 40 sx cement, at 62' with 13 sx cement. Used 60/40 Pozmix 6% gel by Hall	Posal Received by Richard W. Lacey (TECHNICIAN) All Part None X 29 Month: 4 Year: 19 89 at 4400' with 2 sx cement, RECEIVED STATE CORPORATION DIVISION MAY 3 1989 CONSERVATION DIVISION WILLIES Liburton. Recovered 3400' of 5½" casing.
4th plug 5th plug Plugging Coperations ACTUAL PLU 2nd plug 4th plug 5th plug	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?: Completed: Hour:2:30 p.m. Day: GGING REPORT 1st plug set CIBP at 2817' with 100 sx cement, at 1947' with 50 sx cement, at 1006' with 40 sx cement, at 62' with 13 sx cement. Used 60/40 Pozmix 6% gel by Hall (If additional description is	Posal Received by Richard W. Lacey (TECHNICIAN) All Part None X 29 Month: 4 Year: 19 89 at 4400' with 2 sx cement, RECEIVED STATE CORPORATION COMMISSION MAY 3 1989 CONSERVATION DIVISION WICHIES: REMESS
Ath plug Sth plug Plugging Coperations CTUAL PLU 2fid plug 3rd plug 4th plug 5th plug	pump 40 sx cement at 1000', pump 10 sx cement at 40'. Plugging Pro Perations attended by Agent?: Completed: Hour:2:30 p.m. Day: GGING REPORT 1st plug set CIBP at 2817' with 100 sx cement, at 1947' with 50 sx cement, at 1006' with 40 sx cement, at 62' with 13 sx cement. Used 60/40 Pozmix 6% gel by Hall	Posal Received by Richard W. Lacey (TECHNICIAN) All Part None X 29 Month: 4 Year: 19 89 at 4400' with 2 sx cement, RECEIVED STATE CORPORATION DIVISION MAY 3 1989 CONSERVATION DIVISION WILLIES Liburton. Recovered 3400' of 5½" casing.