

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
WICHITA, KANSAS 67217

Rev. 6-3-74
FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

API Number 15 -135 -2586-0000 (of this well)
Lease Owner Sidwell Oil & Gas Co.
Address Box 2475, Pampa, Texas 79065
Lease (Farm Name) Dumler Well No. 1-A
Well Location C SW NE . Sec. 4 Twp. 17S Rge. (E) 26 (W)
County Ness Total Depth 4610 Field Name _____
Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ Rotary D & A X
Well Log attached with this application as required yes
Date and hour plugging is desired to begin 1:00 a.m. 2-16-79

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:

Claude E. Norwood Address P.O. Box 636, Great Bend, Ks. 67530

Plugging Contractor D N B DRILLING, INC. License No. _____
Address 515 R. H. Garvey Building
Wichita, Kansas 67202

Invoice covering assessment for plugging this well should be sent to:

Name Sidwell Oil & Gas Co.
Address Box 2475, Pampa, Texas 79065

and payment will be guaranteed by applicant or acting agent.

STATE RECEIVED
CORPORATION COMMISSION
FEB 23 1979
CONSERVATION DIVISION
Wichita, Kansas

Signed: Bella Prieso
Applicant or Acting Agent
Date: February 16, 1979



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

245 North Water
WICHITA, KANSAS 67202

February 21, 1979

WELL PLUGGING AUTHORITY

Well No.	1
Lease	Dumler "A"
Description	C SW NE Sec. 4-17-26W
County	Ness
Total Depth	4610
Plugging Contractor	DNB Drilling


Sidwell Oil & Gas Co.
Box 2475
Pampa, Texas 79065

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. ~~Len Murrey, 109 West 15th, Hays, Kansas 67601~~
is hereby assigned to supervise the plugging of the above named well.