

10  
STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
800 BITTING BUILDING  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM 15-05705531-00-00

Well Location C S/2 NW NW Sec. 32 Twp. 13 Rge. (E)16 (W)

Field Name (if any) Air Base County Ellis

Lease (Farm Name) Dinkle Well No. 1

Was well log filed with application?  If not, explain circumstances and give available data (Use an additional sheet if necessary)

Date and hour plugging is desired to begin 10-24-62

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired (Use an additional sheet if necessary)

Name of the person on the lease in charge of well for owner

Mervin Sheeks Address Box 268, Claflin, Kansas.

Name of well owner or Acting Agent Hinkle Oil Company

Address 1016 Union Center, Wichita, Kansas.

Invoice covering assessment for plugging this well should be sent to:

Hinkle Oil Company Address 1016 Union Center, Wichita, Kansas.

and payment will be guaranteed by applicant.

J.B. Hinkle  
Operator or Acting Agent

Date 12-18-62



15:051-05531-00-00

JOHN ANDERSON, Jr. Governor  
RICHARD C. BYRD Chairman  
ALVIN F. GRAUERHOLZ Commissioner  
HARRY G. WILES Commissioner  
RAYMOND B. HARVEY Secretary  
CHARLES C. McCARTER Gen. Counsel

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)  
500 Insurance Bldg. 212 N. Market  
WICHITA, KANSAS

October 31, 1962

WELL PLUGGING AUTHORITY

Well No. 1  
Lease Dinkle  
Description C 2/2 NW NW 32-13-16W  
County Ellis

Hinkle Oil Co.  
1016 Union Center  
Wichita, Kansas

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Very truly yours,

J. P. ROBERTS  
Assistant Petroleum Conservation  
Director

Mr. Eldon Petty Box 326 Hays, Kansas  
is hereby assigned to supervise the plugging of the above  
named well.

