


KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
CLOSURE OF SURFACE PIT

Form CDP-4
April 2004
Form must be Typed

Operator Name: John O. Farmer, Inc.	License Number: 5135
Operator Address: 370 West Wichita Avenue P.O. Box 352 Russell, KS 67665	
Contact Person: Marge Schulte	Phone Number: (785) 483 - 3144
Permit Number (API No. if applicable): 147-20,640-00-00	Lease Name & Well No.: Bredemeier "B" # 1
Type of Pit: <input type="checkbox"/> Emergency Pit <input type="checkbox"/> Burn Pit <input type="checkbox"/> Settling Pit <input checked="" type="checkbox"/> Drilling Pit <input type="checkbox"/> Workover Pit <input type="checkbox"/> Haul-Off Pit	Pit Location (QQQQ): SE - NE - NW - SE Sec. 13 Twp. 4S R. 19W <input type="checkbox"/> East <input checked="" type="checkbox"/> West 2030 Feet from <input type="checkbox"/> North / <input checked="" type="checkbox"/> South Line of Section 1330 Feet from <input checked="" type="checkbox"/> East / <input type="checkbox"/> West Line of Section Phillips County
Date of closure: 1-18-12	
Was an artificial liner used? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Sealed with clay soil, native and fresh mud.	
Abandonment procedure of pit: Allow liquid contents to evaporate, let cuttings dry and backfill.	
The undersigned hereby certifies that he / she is <u>President</u> for <u>John O. Farmer, Inc. (Co.)</u> , a duly authorized agent, that all information shown hereon is true and correct to the best of his / her knowledge and belief.	
<u>John O. Farmer III</u> Signature of Applicant or Agent	
Subscribed and sworn to me on this <u>8th</u> day of <u>February</u> , <u>2012</u>	
<u>Margaret A. Schulte</u> Notary Public	
My Commission Expires: 	

RECEIVED
FEB 09 2012
KCC WICHITA