
## STATE OF KANSAS STATE CORPORATION COMMISSION

Make Required Affidavit
Mail or Deliver Report to
Conservation Division
State Corporation Commission
245 North Water
Wichita, KS 67202

FORM CP-4

## WELL PLUGGING RECORD

a, KS 67202	<u> </u>		County.	Sec.19_Tw		
•		IL (CENTINCIAMA	an fantace for—	lines VX	CSSE SW	
	Location as "N	ie/CNWsswa"	<b>or tootage trom</b> Walters Di	rilling Co	ompany	
	Lease Owner_	Schohon	J D.			Well No. 3
	Lease Name		nsurance	Building	Wichita	Kansas 6720
	Office Address.	4-UU L		Des IIvl-1	Drv	Hole .
	Character of V	Well (completed	as Cu, Gas of l	10/16/		i9
	Date well con	npieted			10/16/77	
		r plugging filed_		10/16/		19
		r plugging approv			10/16/77	
	Plugging comm			1/	0/16/77	19
	Plugging comp	pleted				
	Reason for aba	andonment of we	I or producing i	tormation		
						19
	If a producing	g well is abandon	ed, date of last	production		19
				ion Division or		re plugging was cor
Locate well correctly on above Section Plat	menced?		T - 2 M -		Yes	<u> </u>
Section Plat ne of Conservation Agent who se	upervised plugging of th	his well	цео ма	ssey		/.26E
e of Conservation Agent who st ucing formation.		Depth to top	Bottom_	1	Total Depth of	Well 4303 F.
e depth and tlackness of all wa	ter, oil and gas formatio	pns.		•		
					•	ASING RECORD
OIL, CAS OR WATER RECO	NU2			<del></del>		
FORMATION	CONTENT	FROM	TÓ	SIZE	PUT IN	PULLED, DUT
	Surface	0	327	8-5/8	yes	no ·
						*.*
			1			
Describe in detail the manne atroducing it into the hole. Iffect for each plu		plugged, indicate used, state t	ing where the n	nud fluid was pl same and depth	aced and the m	ethod or methods us
ntroducing it into the hole. If	Bottom plu Middle Plu Top and bi 2 sacks in	ng at 660' ig at 240' ridge at 40	with 70 s with 20 s ) with 10	sacks 50/5 sacks 50/5 sacks 50/5 sacks 50	0 Poz 6% 0 Poz 6% 0 Poz 6%	gel gel 6% gel
ntroducing it into the hole. If	Bottom plu Middle Plu Top and bi 2 sacks in	ng at 660' ig at 240' ridge at 40' n rathole	with 70 s with 20 s ) with 10	sacks 50/5 sacks 50/5 sacks 50/5 sacks 50	0 Poz 6% 0 Poz 6% 0 Poz 6%	gel gel 6% gel
ntroducing it into the hole. If	Bottom plu Middle Plu Top and br 2 sacks in Job comple	ig at 660' ig at 240' ridge at 40' n rathole ete at 9:30	with 70 s with 20 s with 10	same and depth sacks 50/5 sacks 50/5 sacks 50 16/77	O Poz 6%	gel gel 6% gel
ntroducing it into the hole. Iffeet for each plu	Bottom plu Middle Plu Top and br 2 sacks in Job comple	ig at 660 ig at 240 iridge at 40 ir rathole ete at 9:30	with 70 s with 20 s with 10 a.m. 10/	same and depth sacks 50/5 sacks 50/5 sacks 50/ 16/77	O Poz 6%	gel gel 6% gel
ntroducing it into the hole. Iffect for each pluse	Bottom plu Middle Plu Top and br 2 sacks in Job comple	ig at 660' ig at 240' ridge at 40' n rathole ete at 9:30'	with 70 s with 20 s with 10 a.m. 10/	same and depth sacks 50/5 sacks 50/5 sacks 50 /16/77	0 Poz 6% 0 Poz 6% 0 Poz 6%	gel gel 6% gel
ntroducing it into the hole. Iffect for each pluster for each plust	Bottom plu Middle Plu Top and br 2 sacks in Job comple	ig at 660' ig at 240' ridge at 40' n rathole ete at 9:30'	with 70 s with 20 s with 10 a.m. 10/	same and depth sacks 50/5 sacks 50/5 sacks 50 /16/77	O Poz 6%	gel gel 6% gel  Vanission 1917 1 1917 1 1918
ntroducing it into the hole. Iffect for each plu	Bottom plu Middle Plu Top and br 2 sacks in Job comple	ig at 660' ig at 240' ridge at 40' n rathole ete at 9:30'	with 70 s with 20 s with 10 a.m. 10/	same and depth sacks 50/5 sacks 50/5 sacks 50 /16/77	O Poz 6%	gel gel 6% gel  Vanission 1917 1 1917 1 1918
me of Plugging Contractor_dress	Bottom plu Middle Plu Top and br 2 sacks in Job comple	ig at 660' ig at 240' ridge at 40' n rathole ete at 9:30 mal description is no rilling Cor ing, Wichin	with 70 s with 20 s with 10 a.m. 10/	same and depth sacks 50/5 sacks 50/5 sacks 50 /16/77	O Poz 6%	gel gel 6% gel  Vanission 1917 1 1917 1 1918
ntroducing it into the hole. If	Bottom plu Middle Plu Top and branch 2 sacks in Job comple Slawson Drawlas Build:	ig at 660' ig at 240' ridge at 40' n rathole ete at 9:30'	with 70 s with 20 s with 10 a.m. 10/	same and depth sacks 50/5 sacks 50/5 sacks 50 /16/77	O Poz 6% O P	gel gel 6% gel Danission Own
me of Plugging Contractor_dress	Bottom plu Middle Plu Top and br 2 sacks in Job comple Slawson Dr Douglas Build:	ig at 660' ig at 240' ridge at 40' n rathole ete at 9:30 maldescription is no rilling Cor ing, Wichi ounty Ol	with 70 s with 20 s ) with 10 ) a.m. 10/	same and depth sacks 50/5 sacks 50/5 sacks 50/7 /16/77	O Poz 6% O P	gel gel 6% gel  Vanission (0)17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
me of Plugging Contractordress200  ATE OF Kansas	Bottom plu Middle Plu Top and br 2 sacks in Job comple (Madditto Slawson Dr. Douglas Build:	ig at 660' ig at 240' ridge at 40' n rathole ete at 9:30' maldescription is no rilling Cor ing, Wichi ounty or	with 70 s with 20 s with 20 s ) with 10 ) a.m. 10/  cossary, use BACK mpany, Inc ta, Kansas  Sedgwick (employee of o	same and depth sacks 50/5 sacks 50/5 sacks 50/7 /16/77	O Poz 6% O P	gel gel 6% gel  Vanission (0)17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
ntroducing it into the hole. If	Bottom plu Middle Plu Top and br 2 sacks in Job comple (Madditto Slawson Dr. Douglas Build:	ig at 660 ig at 240 ig at 240 ir idge at 40 in rathole at 9:30 in its morning. Wiching Coring, William Coring,	with 70 s with 20 s with 20 s ) with 10 ) a.m. 10/  cossary, use BACK mpany, Inc ta, Kansas  Sedgwick (employee of o	same and depth sacks 50/5 sacks 50/5 sacks 50/7 /16/77	O Poz 6% O P	gel gel 6% gel  Vanission (0)17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
introducing it into the hole. If	Bottom plu Middle Plu Top and br 2 sacks in Job comple (Madditto Slawson Dr. Douglas Build:	ig at 660' ig at 240' ridge at 40' n rathole ete at 9:30' maldescription is no rilling Cor ing, Wichi ounty or	with 70 s with 20 s with 20 s with 10 a.m. 10/ cessury, use BACK npany, Inc ta, Kansas Sedgwick (employee of o facts, stateme	same and depth sacks 50/5 sacks 50/5 sacks 50/5 sacks 50/5 facks 50/5 of this sheet) Pro-	O Poz 6% O P	gel gel 6% gel  Vanission (0)17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
introducing it into the hole. If	Bottom plu Middle Plu Top and br 2 sacks in Job comple (Madditto Slawson Dr. Douglas Build:	ig at 660 ig at 240 ig at 240 ir idge at 40 in rathole at 9:30 in its morning. Wiching Coring, William Coring,	with 70 s with 20 s with 20 s ) with 10 ) a.m. 10/  cossary, use BACK mpany, Inc ta, Kansas  Sedgwick Cemployee of o facts, stateme help me God.	same and depth sacks 50/5 sacks 50/5 sacks 50/ /16/77 of this sheet) Pro- s 67202	O Poz 6% O P	gel gel 6% gel  Value Silvi  (QII  10 DIVIS  of the above descripted and the log of
introducing it into the hole. If	Bottom plu Middle Plu Top and bi 2 sacks in Job comple Slawson Di Douglas Build:	ig at 660 ig at 240 ig at 240 ir idge at 40 in rathole ete at 9:30 imal description is nearly illing Coring, Wiching Correct. So is and correct. So is and correct. So	with 70 s with 20 s with 20 s ) with 10 ) a.m. 10/  cossay, use BACK mpany, Inc ta, Kansas  Sedgwick comployee of o facts, stateme help me God.  James C. 200 Doug	same and depth sacks 50/5 sacks 5	O Poz 6% O P	gel gel 6% gel  Value Silvi  (QII)  (
introducing it into the hole. If	Bottom plu Middle Plu Middle Plu Top and brown 2 sacks in Job comples Slawson Drouglas Build:  Sherg Sth, says: That I have that the same are true	ig at 660 ig at 240 ig at 240 ir idge at 40 in rathole ete at 9:30 imal description is nearly illing Coring, Wiching Correct. So is and correct. So is and correct. So	with 70 s with 20 s with 20 s with 10 a.m. 10/ a.m. 10/ cessary, use BACK mpany, Inc ta, Kansas  Sedgwick cemployee of oc facts, stateme help me God.  James C. 200 Doug	same and depth sacks 50/5 sacks 50/5 sacks 50/5 sacks 50/5 sacks 50/5 sacks 50/5 of this sheet) Pro- ce 67202	O Poz 6% O P	gel gel 6% gel  Value Silvi  (QII  10 DIVIS  of the above descripted and the log of
introducing it into the hole. If	Bottom plu Middle Plu Middle Plu Top and brown 2 sacks in Job comples Slawson Drouglas Build:  Sherg Sth, says: That I have that the same are true	ig at 660 ig at 240 ridge at 40 rathole ete at 9:30 mal description is no rilling Coring, Wichigan William Wichigan William W	with 70 s with 20 s with 20 s ) with 10  Da.m. 10/  Consult, use BACK npany, Inc ta, Kansas  Sedgwick (employee of o e facts, stateme help me God.  James C. 200 Doug	same and depth sacks 50/5 sacks 5	o Poz 6% O P	gel gel 6% gel  Value Silvi  (QII  10 DIVIS  of the above descripted and the log of
me of Plugging Contractordress200  ATE OF KansasJames C. Rems. B. being first duly sworn on or over-described well as filed and	Bottom plu Middle Plu Middle Plu Top and brown 2 sacks in Job comples Slawson Drouglas Build:  Sherg Sth, says: That I have that the same are true	ig at 660 ig at 240 ridge at 40 rathole ete at 9:30 mal description is no rilling Coring, Wichigan William Wichigan William W	with 70 s with 20 s with 20 s with 10 a.m. 10/ a.m. 10/ cessary, use BACK mpany, Inc ta, Kansas  Sedgwick cemployee of oc facts, stateme help me God.  James C. 200 Doug	same and depth sacks 50/5 sacks 5	o Poz 6% O P	gel gel 6% gel  ONNICSION ONNICSION ON DIVIS  of the above descripted and the log of  Lita, Ks.6720
introducing it into the hole. If	Bottom plu Middle Plu Top and branch 2 sacks in Job comples Slawson Dranch Build:  Slawson Dranch Build:  Sherg Sth., says: That I have that the same are true before me this 20	ig at 660 ig at 240 ridge at 40 rathole ete at 9:30 mal description is no rilling Coring, Wichigan William Wichigan William W	with 70 s with 20 s with 20 s ) with 10  Da.m. 10/  Consult, use BACK npany, Inc ta, Kansas  Sedgwick (employee of o e facts, stateme help me God.  James C. 200 Doug	same and depth sacks 50/5 sacks 5	o Poz 6% O P	gel gel 6% gel  Value Silvi  (QII  10 DIVIS  of the above descripted and the log of
introducing it into the hole. If	Bottom plu Middle Plu Middle Plu Top and bra 2 sacks in Job comple Slawson Draglas Build:  Sherg ath, says: That I have that the same are true	ig at 660 ig at 240 ridge at 40 rathole ete at 9:30 mal description is no rilling Coring, Wichigan William Wichigan William W	with 70 s with 20 s with 20 s ) with 10  Da.m. 10/  Consult, use BACK npany, Inc ta, Kansas  Sedgwick (employee of o e facts, stateme help me God.  James C. 200 Doug	same and depth sacks 50/5 sacks 5	o Poz 6% O P	gel gel 6% gel  ONNICSION ONNICSION ON DIVIS  of the above descripted and the log of  Lita, Ks.6720



## DRILLERS LOG

OPERATOR:

Walters Drilling Company 400 Insurance Building Wichita, Kansas 67202

LEASE:

Schaben No.3

C SE SW Sec. 19-17S-24W Ness County, Kansas

CONTRACTOR:

Slawson Drilling Company, Inc.

200 Douglas Building Wichita, Kansas 67202

COMMENCED:

10/8/77

COMPLETED:

10/16/77

RTD:

43651

CASING:

New 8.5/8" set at 327' with 200 sacks cement

0' to 332' 12½" Surface Hole (Clay, Sand, Shale)

332' to 1090' Shale & Sand Streaks

1090' to 1340' Sand 1340' to 1633' Shale 1633' to 1664' Anhydrite

1664' to 2225' Shale & Shells

to 2385' Shale & Shells with lime strks. 2225

2385' to 2880' Shale & Lime 2880' to 3480' Lime & Shale 3480' to 3685' Shale & Lime

3685' to 4005' Lime & Shale 4005 to 4265 Lime

4265' to 4302' Lime & Shale

4302' to 4365' Lime

4365' RTD

State of Kansas

County of Sedgwick

I, James C. Remsberg hereby state that the above and foregoing is a true and accurate copy of the log of the Schaben No.3 well for Walters Drilling Company.

Subscribed and sworn to me this 26th day of October, 1977

Mary Low Taylor,

My commission expires January 17, 1981

