

1050317

API NUMBER 15- 135-22,643-00-00 *R*

To: STATE CORPORATION COMMISSION
CONSERVATION DIVISION - PLUGGING SECTION
200 COLORADO DERBY BUILDING
WICHITA, KANSAS 67202

250' E of N/2 NW, SEC. 24 ; T 17 S, R 24 W/E
3710 *ESL* feet from ~~N/2~~ section line
3960 *FEV* feet from ~~N/2~~ section line

TECHNICIAN'S PLUGGING REPORT

Operator License # 5088

Lease Name Kirk Rufenacht Well # 1

Operator: John J. Darrah, Jr.

County Ness

Name & Address 405 Century Plaza Building

Well Total Depth 4500 *146.25* feet

Wichita, KS 67202

Conductor Pipe: Size _____ feet

Surface Casing: Size 8 5/8 feet 325

Abandoned Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ D&A

Other well as hereinafter indicated _____

Plugging Contractor Mallard Drilling Co., Inc. License Number 5651

Address 405 Century Plaza Building, Wichita, KS 67202

Company to plug at: Hour: 11:30 am Day: 23 Month: August Year: 19 84

Plugging proposal received from Wayne Stout

(company name) Mallard (phone) 316-263-8218

were: _____ to fill hole with heavy mud and spot cement through drill pipe

1st plug at 840' with 60 sx cement

2nd plug at 360' with 40 sx cement
solid bridge

3rd plug hulls - plug at 40' -- cement to surface with 10 sx cement

5th plug to circulate rat hole with 10 sx cement

6th plug to circulate mouse hole with 10 sx cement

Plugging Proposal Received by *Richard W. Lacey*
(TECHNICIAN)

Plugging Operations attended by Agent?: All Part _____ None _____

Operations Completed: Hour: 1:45 pm Day: 23 Month: August Year: 19 84

ACTUAL PLUGGING REPORT 1st plug at 840' with 60 sx cement, 2nd plug at 360' with

40 sx cement, 3rd & 4th plugs - solid bridge - hulls - plug at 40' -- cement to surface

with 10 sx cement, 5th plug to circulate rat hole with 10 sx cement, 6th plug to

circulate mouse hole with 10 sx cement

Remarks: Used 60/40 Pozmix 2% gel 3% cc by Allied.

(If additional description or information is necessary, use BACK of this form.)

INVOICED

DATE 9-10-84

INV. NO. 3603

SEP 04 1984
09-04-1984
CONSERVATION DIVISION
Wichita, Kansas

Richard W. Lacey
(TECHNICIAN)