

15-135-20800-0001  
KCC OIL/GAS REGULATORY OFFICE

*Jim H.*

Date 4-19-2001

- New Situation
- Response to Request
- Follow-up

Operator Palemino # \_\_\_\_\_

Address \_\_\_\_\_

Location SE, Sec 15, T 18 S, R 26 W

Lease Walters 'A' Well # 0000-1

Phone No. \_\_\_\_\_  
Oper. \_\_\_\_\_ Other \_\_\_\_\_

County Ness

Reason for Investigation: Witness Airt II

Problem: \_\_\_\_\_

Person(s) Contacted: \_\_\_\_\_

Findings: 8 5/8" @ 330'

T.D. 4665'

5 1/2" @ 4664' w/ 1505x5.

Port Callan at 1922' w/ 2005x5 - 5MDS 27% CC 1/4 # F10

Mixed all cement and 255x5 went to pit. (MIDCON II)

photos taken: \_\_\_\_\_

Action/Recommendations: None Cement Circulated

RECEIVED  
STATE CORPORATION COMMISSION

APR 27 2001

04-27-01

CONSERVATION DIVISION  
Topeka, Kansas

- Lease Inspection
- Complaint
- Field Report

By Michael J. Mauer

Retain 1 copy Joint District Office  
Send one copy Conservation Division